



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 8964M

| Qty | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                           |                   |
| 1   | FRONT BUMPER  | TO REPAIR SEE LABOUR | 1,101.40                  | -                 |
| 1   | FRONT BUMPER SIDE HOLDER  | NOT NECESSARY        | 36.50                     | -                 |
| 1   | FRONT FENDER  | TO REPAIR SEE LABOUR | 789.90                    | -                 |
| 1   | HEADLAMP  | NOT NECESSARY        | 1,298.10                  | -                 |
| 1   | FRONT WING MIRROR   | CRACKED              | 682.70                    | 682.70            |
| 1   | FRONT DOOR  | TO REPAIR SEE LABOUR | 1,042.50                  | -                 |
| 1   | FRONT DOOR HANDLE   | TO REPAIR SEE LABOUR | 189.50                    | -                 |
|     | LESS 20% DISCOUNT   |                      | -1,028.12                 | -136.54           |
|     |   |                      | 4,112.48                  | 546.16            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>  |                      |                           |                   |
| 1   | SET FRONT BUMPER CLIPS (SN)   | NOT NECESSARY        | 30.00                     | -                 |
| 1   | FRONT BUMPER LOWER SPOILER (SN)   | TO REPAIR SEE LABOUR | 1,400.00                  | -                 |
| 1   | FRONT DOOR VISOR (SN)   | NOT NECESSARY        | 100.00                    | -                 |
| 1   | SET FRONT DOOR BLACK TAPE (SN)  | NOT NECESSARY        | 60.00                     | -                 |
|     |   |                      | 1,590.00                  | -                 |
|     | <b><u>LABOUR</u></b>  |                      |                           |                   |
|     | PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT FENDER, FRONT DOOR, FRONT DOOR HANDLE AND FRONT BUMPER LOWER SPOILER. |                      | 1,000.00                  | 100.00            |
|     | SPRAY PAINTING TO AFFECTED AREA.  |                      | 2,000.00                  | 100.00            |
|     | WIRING CHECK.   | NOT NECESSARY        | 50.00                     | -                 |
|     | TO TRANSFER FRONT DOOR FITTINGS.  | NOT NECESSARY        | 150.00                    | -                 |
|     | TO APPLY TUFF COAT.   | NOT NECESSARY        | 150.00                    | -                 |
|     |   |                      | 3,350.00                  | 200.00            |
|     | <b>GRAND TOTAL</b>  |                      | <b>9,052.48</b>           | <b>746.16</b>     |

Report Ref No. CS/LIP24110538/Aqh3e2(N)



|   |  |  |        |
|---|--|--|--------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | 600.00 |
|---|--|--|--------|

Report Ref No. CS/LIP24110538/Aqh3e2(N)

MARKET VALUE: \$74,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,782.00=NETT VALUE: \$59,218.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.