

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110539/UUA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0004995_03
Claimant Vehicle No : SNK676B **Insured Vehicle No :** CB8483R
Date of Loss: 02/10/2024 Nature of Claim: TP Claim No: MCV2024D0011663

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNK676B**
Make & Model: TOYOTA ALPHARD, 2.5 HYBRID SR C CVT (A) Engine No: 2AR2848503
Reg. Date: 17/03/2023 (Man. Year: 2022) Chassis No: AYH300152330
Colour: White Odometer: 127762 km
Engine Capacity: 2493 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
Front Left Side: 7 mm Rear Left Side: 7 mm
Front Right Side: 7 mm Rear Right Side: 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 8,901.20 | 4,330.38 | 4,570.82 | 51.35 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,560.00 | 1,730.00 | 830.00 | 32.42 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,461.20 | 6,060.38 | 5,400.82 | 47.12 |
| Approved Total (Overridden) (S\$) | | 4,800.00 | | |
| Nett Amount (S\$) | 11,461.20 | 4,800.00 | 6,661.20 | 58.12 |
| + Doc/Search Fee (S\$) | | 27.25 | | |
| Nett Liability (S\$) | | 4,827.25 | | |

INSPECTION

Date of Assignment: 26/11/2024
Date Inspected: 26/11/2024 Inspected At: T K Lee Automotive Pte Ltd (HQ)
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 24 Dec 2024) |
| Parts: | M1-MPV | TOYOTA ALPHARD 2.5 HYBRID SR C CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNK676B) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|--------------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Dented / Bent | 2,126.20 FL | *2,126.20 FL |
| 2 | 1 | | *TAILGATE EMBLEM ALPHARD | Necessary | 110.25 FL | *110.25 FL |
| 3 | 1 | | *TAILGATE EMBLEM E-FOUR | Necessary | 89.95 FL | *89.95 FL |
| 4 | 1 | | *TAILGATE EMBLEM HYBRID | Necessary | 89.95 FL | *89.95 FL |
| 5 | 1 | | *TAILGATE GLASS | Not Necessary | 1,310.59 FL | *- FL |
| 6 | 1 | | *SET TAILGATE GLASS MOULDING | Necessary | 182.63 FL | *182.63 FL |
| 7 | 1 | | *TAILGATE INNER LOCK | Serviceable | 681.45 FL | *- FL |
| 8 | 1 | | *TAILGATE INNER TRIM BOARD | Not Necessary | 831.10 FL | *- FL |
| 9 | 1 | | *TAILGATE W/STRIP | Not Necessary | 361.43 FL | *- FL |
| 10 | 2 | | *TAILLAMP LOWER GARNISHES -R/L | Not Necessary | 962.66 FL | *- FL |
| 11 | 1 | | *REAR BUMPER | Dented / Deformed | 1,366.63 FL | *1,029.10 FL |
| 12 | 2 | | *REAR BUMPER SIDE RETAINERS -R/L | Not Necessary | 220.50 FL | *- FL |
| 13 | 1 | | *REAR BUMPER PDC SENSOR (2 PCS) | Malfunction (1 PCS ONLY) | 882.66 FL | *441.33 FL |
| 14 | 1 | | *REAR END PANEL | Dented / Bent | 971.10 FL | *971.10 FL |
| 15 | 1 | | *REAR SMARY KEYLESS ANTENNA | Not Necessary | 181.90 FL | *- FL |
| 16 | 1 | | *REAR SMARY KEYLESS BUZZLE | Not Necessary | 192.60 FL | *- FL |
| 17 | 1 | | *SET TAILGATE GLASS SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 18 | 1 | | *SET REAR BUMPER CLIP | Necessary | 50.00 FS | *30.00 FS |
| 19 | 1 | | *REAR BUMPER CHROME PLATE | Dented / Bent | 850.00 FS | *480.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------|----------|
| Sub Total (\$\$) | 11,541.60 | 5,590.51 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 2,640.40 | 1,260.13 |
| Total Parts (\$\$) | 8,901.20 | 4,330.38 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACE REAR TAILGATE GLASS | New | 180.00 | 120.00 |
| 2 | TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE | New | 150.00 | 60.00 |
| 3 | TO CHECK REAR ELECTRICAL WIRING | New | 50.00 | 20.00 |
| 4 | TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR | New | 120.00 | 80.00 |
| 5 | TO TUFF KOTE | New | 80.00 | 50.00 |
| 6 | TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS | New | 1,080.00 | 800.00 |
| 7 | TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS | New | 900.00 | 600.00 |
| Gross Labour Cost (\$\$) | | | 2,560.00 | 1,730.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >