



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24060298/Eqh3e2

Date: 30/08/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHB 3819E | Veh. Inspected | SKX 3647H |
| Policy No. | D-24101860MFCT | Coverage | 0 |
| Claim No. | D24005550MFCT | Excess | \$0.00 |
| Assign From | AINI | Assign Date | 27/06/2024 |

2. Vehicle Details

| | | | |
|-----------------|-------------------|--------------|----------|
| Make & Model | TOYOTA CAMRY | C.C | 1998 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | MR053DK5100104797 | Colour | WHITE |
| Odometer | 126847 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|------------|--------|--------------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 |
| R/H Rear Tyre | 215/60 R16 | DUNLOP | 6 |
| L/H Rear Tyre | 215/60 R16 | DUNLOP | 6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 23/06/2024 | Inspection Date | 28/06/2024 |
| Survey held at | INDECO ENGINEERS PTE LTD - BLK 2 DEFU SOUTH STREET 1 #04-08 JTC DEFU INDUSTRIAL CITY SINGAPORE 533755 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days