



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060298/Eqh3e2
16 RAFFLES QUAY	Date:	30/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3819E	Veh. Inspected	SKX 3647H
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005550MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	27/06/2024

2. Vehicle Details

Make & Model	TOYOTA CAMRY	C.C	1998
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	MR053DK5100104797	Colour	WHITE
Odometer	126847 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R16	DUNLOP	6
L/H Front Tyre	215/60 R16	DUNLOP	6
R/H Rear Tyre	215/60 R16	DUNLOP	6
L/H Rear Tyre	215/60 R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/06/2024	Inspection Date	28/06/2024
Survey held at	INDECO ENGINEERS PTE LTD - BLK 2 DEFU SOUTH STREET 1 #04-08 JTC DEFU INDUSTRIAL CITY SINGAPORE 533755		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days