



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501935

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:KAREN TAN

INV Date 01/04/2025
Reference CD/FCI24110541/Uma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBV 9459L
Insured Veh. SHD 4595H
Claim No. D24009756MFCT
Policy No. D-24101861MFCT
Accident Date 03/11/2024
Inspection Date 26/11/2024

Description	Total
Third Party Express Settlement	300.00
Subtotal	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:KAREN TAN		Ref: CD/FCI24110541/Uma3q2(N) Date: 01/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4595H	Veh. Inspected	FBV 9459L
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24009756MFCT	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	26/11/2024
2. Vehicle Particulars & Condition			
Make & Model	HONDA FUTURE 125	c.c	125
Engine No.	HIDDEN	Year of Reg.	2024
Chassis No.	RLHJC7659NY347391	Colour	GREY
Odometer	6866 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70-90-17	INOUE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80-90-17	INOUE	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/11/2024	Inspection Date	26/11/2024
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBV 9459L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	SERVICEABLE	155.00	-
1	BRAKE LEVER	CUT	80.00	80.00
1	BALANCER RH	CUT	55.00	55.00
1	MIRROR RH	CUT	75.00	75.00
1	MUDGUARD	CUT	145.00	145.00
1	BRAKE PADDLE	CUT	85.00	85.00
1	FOOTREST BAR	BENT	85.00	85.00
1	FOOTREST RUBBER	TORN	65.00	65.00
1	REAR FOOTREST RH	CUT	85.00	85.00
1	EXHAUST COVER	CUT	95.00	95.00
1	STARTER SWITCH	MISSING	95.00	95.00
1	FORK	SERVICEABLE	480.00	-
1	FOKR LOWER CLAMP	NOT NECESSARY	280.00	-
1	STEERING CONE	NOT NECESSARY	165.00	-
1	EXHAUST PIPE	DAMAGED	580.00	580.00
1	REAR MUDGUARD	DISTORTED	185.00	185.00
1	REAR BODY FRAME ALIGHTMI	NOT NECESSARY	450.00	-
1	REAR BODY FRAME RESPRAY	NOT NECESSARY	350.00	-
	LESS 10% DISCOUNT		-	-163.00
			3,510.00	1,467.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX (SN)	CUT	240.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
			270.00	230.00
	<u>LABOUR</u>			
	LABOUR .		580.00	300.00
			580.00	300.00
	GRAND TOTAL		4,360.00	1,997.00

Report Ref No. CD/FCI24110541/Uma3q2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00
---	--	--	-----------------

Report Ref No. CD/FCI24110541/Uma3q2(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L




PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 18 of 18)

PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L



PHOTOGRAPHS FOR VEHICLE NO. : FBV 9459L

