

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110543/KMA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220015963
Claimant Vehicle No : SNG9595M **Insured Vehicle No :** GBJ2901K
 Date of Loss: 23/11/2024 Nature of Claim: TP Claim No: 8274937117SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG9595M**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT SENSING (A) Engine No: L15B6021253
 Reg. Date: 22/01/2021 (Man. Year: 2019) Chassis No: GK82101067
 Colour: Metallic Grey Odometer: 109214 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,944.48	4,032.20	1,912.28	32.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,310.00	1,250.00	48.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,504.48	5,342.20	3,162.28	37.18
+ GST 9.00/9.00% (S\$)	765.40	480.80	284.60	37.18
Nett Amount (S\$)	9,269.88	5,823.00	3,446.88	37.18
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,550.25		

INSPECTION

Date of Assignment: 26/11/2024
 Date Inspected: 26/11/2024 Inspected At: Alan's United Auto Pte Ltd (HQ)
 Singapore 575642
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR W/S GLASS	Shattered	795.40 FL	*795.40 FL
2	1		*REAR W/S GLASS MOULDING	Necessary	67.50 FL	*67.50 FL
3	1		*REAR WIPER MOTOR	Serviceable	300.90 FL	*- FL
4	1		*REAR WIPER ARM	Serviceable	43.50 FL	*- FL
5	1		*REAR WIPER BLADE	Serviceable	46.80 FL	*- FL
6	1		*TAIL GATE	Bent	970.30 FL	*970.30 FL
7	1		*TAIL GATE INNER LOCK	Dented	178.20 FL	*178.20 FL
8	1		*TAIL GATE RUBBER	Distorted /Dented	117.70 FL	*117.70 FL
9	1		*TAIL GATE INNER TRIM	Mtg Cracked	194.60 FL	*194.60 FL
10	1		*TAIL GATE OPEN POCKET	Dented	16.50 FL	*16.50 FL
11	1		*TAIL GATE OUTER GARNISH	Warped	372.00 FL	*372.00 FL
12	2		*TAIL GATE LAMP	N/S Crumpled / O/S Cracked	735.00 FL	*735.00 FL
13	1		*TAIL GATE SHUTTLE EMBLEM	Necessary	49.70 FL	*49.70 FL
14	2		*TAIL GATE LICENSE PLATE LAMP	Serviceable	270.00 FL	*- FL
15	1		*TAILLAMP	O/S Cut	806.00 FL	*403.00 FL
16	1		*REAR END PANEL	Repair	444.90 FL	*- FL
17	1		*END PANEL TOP GARNISH	Dented	90.00 FL	*90.00 FL
18	1		*REAR BUMPER FASCIA	Buckled	864.10 FL	*864.10 FL
19	1		*REAR BUMPER TOP CHROME	Necessary	76.40 FL	*76.40 FL
20	1		*REAR BUMPER TOW COVER	Dented	16.10 FL	*16.10 FL
21	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	400.00 FS	*- FS
22	1		*REAR REVERSE CAMERA	Serviceable	300.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
24	1		*REAR NO PLATE WITH BOX	Dented	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,235.60	5,021.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,291.12	989.30
Total Parts (\$)	5,944.48	4,032.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	150.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	30.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	1,200.00	600.00
5	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,560.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >