

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|------------------------|---|-------------------|------------------------------|
| MS | LONPAC INSURAN | NCE BHD | Ref: | CS3/LPC24110545/Enh3m4 |
| | 300 BEACH ROAD | | Date: | 06/12/2024 |
| | #17-04/07 THE CO | NCOURSE SINGAPORE 199555 | Code: | LPC2 |
| 1. Policy Particulars :- PRE-REPAIR SURVEY | | | | |
| | Insured Veh. | GBG 5067P | Veh. Inspected | SMF 8842Z |
| | Policy No. | Z24VC05026052 | Coverage | 0 |
| | Claim No. | 24/24/24/VC05/030230 | Excess | \$0.00 |
| | Assign From | ERIC WOO | Assign Date | 26/11/2024 |
| 2. Vehicle Details | | | | |
| | Make & Model | RENAULT SCENIC | C.C | 1461 |
| | Engine No. | K9KF649D038942 | Year of Reg. | 28/11/2018 |
| | Chassis No. | VF1RFA00560211830 | Colour | WHITE |
| | Odometer | 106619 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | General | GOOD |
| | Modification(s) | RIMS: SPORTS RIM | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) |
| | R/H Front Tyre | 195/55R20 | GITI | 5 |
| | L/H Front Tyre | 195/55R20 | GITI | 5 |
| | R/H Rear Tyre | 195/55R20 | GITI | 5 |
| | L/H Rear Tyre | 195/55R20 | GITI | 5 |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| 5. | 5. General Information | | | |
| | Accident Date | 25/11/2024 | Inspection Date | , |
| | Survey held at | AP AUTO GARAGE - 5 KAKI BUKIT 417800 | ROAD 4 #06-46, SY | NERGY @ KAKI BUKIT SINGAPORE |
| 5a. Remarks | | | | |
| A)MARKET VALUE: \$53,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,887.00=NETT VALUE: \$32,113.00 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. E) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000 | | | | |
| 5b. Estimate Days of Repair | | | | |

CTY

STEVE CHEN TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.