

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110548/RQP3M4**Date:** 12/08/2025REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SNE9505J**Insured Vehicle No :** SGD3819G

Date of Loss: 31/10/2024

Nature of Claim: TP

Claim No: DMPC2401481H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNE9505J**

Make & Model: HONDA E ADVANCE, (A)

Engine No: HIDDEN

Reg. Date: 22/04/2022 (Man. Year: 2020)

Chassis No: JHMZC7840LX203195

Colour: Blue

Odometer: 16023 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 ZR17

Rear Tyre Size: 205/45 ZR17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,682.50	7,058.60	8,623.90	54.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,230.00	4,490.00	2,740.00	37.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,912.50	11,548.60	11,363.90	49.60
+ GST 9.00/9.00% (S\$)	2,062.13	1,039.37	1,022.76	49.60
Nett Amount (S\$)	24,974.63	12,587.97	12,386.66	49.60

INSPECTION

Date of Assignment: 26/11/2024

Date Inspected: 26/11/2024

Inspected At:

Eurokars Auto Pte Ltd (HQ)

27A Tanjong Penjuru

Singapore 609042

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

COE category this vehicle falls under (i.e., A or B)
(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$8,758.70 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2025)
Parts:	144	HONDA E ADVANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE9505J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,434.70 F	*1,434.70 F
2	1		*BONNET HINGE LH	Bent	114.20 F	*114.20 F
3	1		*BONNET HINGE RH	Bent	114.20 F	*114.20 F
4	2		*BONNET DAMPER	Activated	342.60 F	*342.60 F
5	1		*BONNET GARNISH CENTER SQUARE	* Check	329.40 F	*- F
6	1		*COWL TOP GARNISH	* Check	473.70 F	*- F
7	1		*BONNET TOP COVER CENTER	* Check	3,300.20 F	*- F
8	1		*FRONT BUMPER	Deformed	1,405.30 F	*1,405.30 F
9	1		*FRONT BUMPER LOWER GRILLE	Scratched	490.50 F	*490.50 F
10	1		*FRONT BUMPER LOWER SPOILER	* Check	178.10 F	*- F
11	1		*FRONT BUMPER CENTER COVER	Deformed	1,716.90 F	*1,716.90 F
12	1		*FRONT BUMPER RETAINER LH	Not Necessary	35.20 F	*- F
13	1		*FRONT BUMPER RETAINER RH	Necessary	35.20 F	*35.20 F
14	1		*FRONT SUPPORT UPPER	* Check	826.50 F	*- F
15	10		*FRONT BUMPER CLIPS	Necessary	42.00 F	*42.00 F
16	1		*HEADLIGHT RH	Broken	73.90 F	*73.90 F
17	1		*HEADLIGHT BRACKET RH	Cracked	73.90 F	*73.90 F
18	1		*FRONT GRILLE PROTECTOR	* Check	150.80 F	*- F
19	1		*FRONT FENDER RH	Bent	645.20 F	*645.20 F
20	1		*FRONT FENDER UNDERSHIELD RH	Deformed	466.80 F	*466.80 F
21	1		*FRONT FENDER A-PILLAR TRIM RH	* Check	409.80 F	*- F
22	1		*FRONT FENDER UNDERCOVER RH	* Check	288.90 F	*- F
23	1		*FENDER PANEL RH	* Check	823.50 F	*- F
24	1		*FOGLAMP RH	* Check	576.20 F	*- F
25	1		*WASHER TANK	Deformed	83.20 F	*83.20 F
26	1		*STEERING GEAR (NPA)	* Check	0.00 F	*- F
27	2		*STEERING GEAR BOLT (NPA)	* Check	0.00 F	*- F
28	1		*TIE ROD END RH (NPA)	* Check	0.00 F	*- F
29	2		*TIE ROD END NUT (NPA)	* Check	0.00 F	*- F
30	1		*FRONT SHOCK ABSORBER RH (NPA)	* Check	0.00 F	*- F
31	1		*SHOCK ABSORBER MOUNTING RH (NPA)	* Check	0.00 F	*- F
32	1		*MOUNTING BOLT (NPA)	* Check	0.00 F	*- F
33	1		*STABILIZER LINK RH (NPA)	* Check	0.00 F	*- F
34	1		*STABILIZER NUT (NPA)	* Check	0.00 F	*- F
35	1		*FRONT LOWER ARM RH (NPA)	* Check	0.00 F	*- F
36	2		*LOWER ARM BOLT (NPA)	* Check	0.00 F	*- F
37	1		*WHEEL HUB (NPA)	* Check	0.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*WHEEL HUB BEARING (NPA)	* Check	0.00 F	*- F
39	1		*KNUCKLE ARM RH (NPA)	* Check	0.00 F	*- F
40	1		*ABS SENSOR RH (NPA)	* Check	0.00 F	*- F
41	1		*DRIVESHAFT RH (NPA)	* Check	0.00 F	*- F
42	1		*FRONT RIM RH	* Check	1,151.60 F	*- F
43	1		*FRONT REINFORCEMENT (NPA)	Bent	0.00 F	*- F
44	1		*FRONT LICENCE PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
45	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					F=Franchise part. S=SpcNett.	
					Total Parts (\$\$)	15,682.50 7,058.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REPLACE BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT FENDER PANEL RH, SUPPORT UPPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,800.00	1,400.00
2	TO RESPRAY BONNET, FRONT BUMPER, FRONT FENDER RH, LOWER SPOILER,FENDER PANEL RH, FRONT DOOR RH	New	2,600.00	2,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	150.00	80.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	80.00	60.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	250.00	250.00
6	TO TRANSFER THE FRONT BUMPER SENSORS	New	250.00	100.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
8	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY	New	250.00	250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	200.00
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	250.00	0.00
* Check				
Gross Labour Cost (\$\$)			7,230.00	4,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >