



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLA 2744B

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP LH (N)	SCRATCHED / CRACKED	\$6,079.62	\$5,322.20
1	FRONT BUMPER (N)	CRACKED / TORN	\$935.10	\$935.10
1	FRONT BUMPER FOG LAMP LH (N)	CRACKED	\$329.12	\$329.12
1	FRONT BUMPER FOG LAMP COVER LH (N)	NOT NECESSARY	\$195.65	\$0.00
1	FRONT BUMPER PDC SENSOR (N)	SERVICEABLE	\$509.48	\$0.00
2	FRONT BUMPER SIDE RETAINER RH / LH @\$125.89 (N)	N/S CRACKED / O/S NOT NECESSARY	\$251.78	\$125.89
	LESS 10.00%		(\$830.08)	(\$671.23)
			\$7,470.67	\$6,041.08
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SPONGE TAPE (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$50.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS		\$400.00	\$200.00
	TO SPRAY PAINT ON ACCIDENT PORTION		\$700.00	\$500.00
	TO CHECK WIRING		\$30.00	\$20.00
			\$1,130.00	\$720.00
GRAND TOTAL			\$8,650.67	\$6,761.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,400.00
Report Ref No: CS/AGI24060299/Uqh3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser