



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060299/Uqh3
(BUDGET DIRECT INSURANCE)	Date:	28/06/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMM 215A	Veh. Inspected	SLA 2744B
Policy No.	P10756779R02	Coverage	0
Claim No.	C10030065/HY	Excess	\$0.00
Assign From	MICHAEL	Assign Date	28/06/2024

### 2. Vehicle Details

Make & Model	TOYOTA LEXUS ES300H (A)	C.C	2494
Engine No.	2AR1433193	Year of Reg.	26/02/2016
Chassis No.	JTHBW1GG202116822	Colour	SILVER
Odometer	160518 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40ZR19	MICHELIN	7
L/H Front Tyre	245/40ZR19	MICHELIN	7
R/H Rear Tyre	245/40ZR19	MICHELIN	7
L/H Rear Tyre	245/40ZR19	MICHELIN	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	20/06/2024	Inspection Date	28/06/2024
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days