

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110555/EMA3Q2
Date: 04/02/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070080723
Claimant Vehicle No : SHB5025R Insured Vehicle No : GBE4803Z
Date of Loss: 26/11/2024 Nature of Claim: TP Claim No: 4506289496SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5025R
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS096342
Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503572615
Colour: Maroon Odometer: 999999 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: GREENTRAC 5 mm Rear Left Side: GREENTRAC 5 mm
Front Right Side: GREENTRAC 5 mm Rear Right Side: GREENTRAC 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,889.42	6,282.47	17,606.95	73.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,144.00	1,256.00	1,888.00	60.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,033.42	7,538.47	19,494.95	72.11
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	27,033.42	4,500.00	22,533.42	83.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/11/2024
Date Inspected: 26/11/2024 Inspected At: STRIDES PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ)
23 CHANGI SOUTH AVE 2
Singapore 486443
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Broken	560.30 F	*420.22 F
2	1		*ABSORBER FR BUMPER (DISC 25%)	Broken	85.90 F	*64.43 F
3	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	98.70 F	*74.03 F
4	1		*GRILLE SUB-ASSY (DISC 25%)	Broken	374.40 F	*280.80 F
5	1		*HOOD SUB-ASSY (DISC 25%)	Dented	1,066.30 F	*799.72 F
6	1		*FENDER SUB-ASSY ,FR RH (DISC 25%)	Necessary	1,060.70 F	*795.53 F
7	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	59.10 F	*44.33 F
8	1		*LAMP ASSY FOG RH (DISC 25%)	Missing	1,029.90 F	*772.43 F
9	1		*UNIT HEADLAMP RH (DISC 25%)	Broken	2,852.40 F	*2,139.30 F
10	10		*CLIPS PIECE ,FRT BUMPER (DISC 25%)	Necessary	48.00 F	*36.00 F
11	1		*WIPER WASHER JAR (DISC 25%)	Crushed	236.90 F	*177.68 F
12	1		*SET COVER ASSY ENGINE UNDER CENTER (DISC 25%)	Broken	511.20 F	*383.40 F
13	1		*COVER ASSY ENGINE (DISC 25%)	Broken	201.00 F	*150.75 F
14	1		*BRACKET ,FR BUMPER (DISC 25%)	Broken	111.80 F	*83.85 F
15	1		*NUMBER PLATE (SN)	Bent	35.00 F	*35.00 F
16	1		*NUMBER PLATE FRAME (SN)	Crushed	25.00 F	*25.00 F
17	1		*PAD ,FR WHEEL LH	Not Necessary	65.00 F	*- F
18	1		*SUPPORT ,FR BUMPER RH	Not Necessary	86.20 F	*- F
19	1		*SUPPORT ,FR BUMPER LH	Not Necessary	86.20 F	*- F
20	1		*COVER FR BUMPER RH	Not Necessary	31.80 F	*- F
21	1		*COVER FR BUMPER LH	Not Necessary	31.80 F	*- F
22	1		*BRACKET FR BUMPER	Not Necessary	111.80 F	*- F
23	1		*REINFORCEMENT FRONT UPPER	Not Necessary	773.90 F	*- F
24	1		*EXTENSION SUB-ASSY LH	Not Necessary	129.90 F	*- F
25	1		*EXTENSION SUB-ASSY RH	Not Necessary	129.90 F	*- F
26	1		*REINFORCEMENT FRONT LOWER	Not Necessary	265.90 F	*- F
27	1		*ABSORBER ,FR BUMPER LOWER	Not Necessary	143.60 F	*- F
28	1		*SEAL ,HOOD TO FR END	Not Necessary	55.80 F	*- F
29	1		*GRILLE RADIATOR	Not Necessary	183.90 F	*- F
30	1		*COVER ASSY ENGINE	Not Necessary	201.00 F	*- F
31	1		*SET COVER ASSY ENGINE UNDER CENTER	Not Necessary	511.20 F	*- F
32	1		*COVER ENGINE UNDER SIDE RH	Not Necessary	86.20 F	*- F
33	1		*COVER ENGINE UNDER SIDE LH	Not Necessary	86.20 F	*- F
34	1		*UNIT HEADLAMP LH	Not Necessary	2,852.40 F	*- F
35	1		*COMPUTER SUB-ASSY HEADLAMP RH NO.1	Not Necessary	1,039.90 F	*- F
36	1		*INSULATOR HOOD	Not Necessary	444.40 F	*- F
37	1		*COVER RADIATOR	Not Necessary	254.70 F	*- F
38	1		*HINGE ASSY HOOD RH	Not Necessary	63.70 F	*- F
39	1		*HINGE ASSY HOOD LH	Not Necessary	63.70 F	*- F
40	1		*LOCK ASSY HOOD	Not Necessary	146.10 F	*- F
41	1		*SUPPORT S/A RH	Not Necessary	265.10 F	*- F
42	1		*SUPPORT S/A LH	Not Necessary	265.10 F	*- F
43	1		*WIPER WASHER JAR	Not Necessary	236.90 F	*- F
44	2		*RETAINER FR BUMPER LH & RH	Not Necessary	9.50 F	*- F
45	1		*LAMP ASSY FOG LH	Not Necessary	1,029.90 F	*- F
46	1		*INSULATOR HOOD CLIP	Not Necessary	3.10 F	*- F
47	1		*BOLT HOOD LOCK	Not Necessary	11.20 F	*- F
48	1		*SUPPORT S/A UPPER	Not Necessary	408.50 F	*- F
49	1		*SUPPORT RADIATOR UPPER LH	Not Necessary	85.20 F	*- F
50	1		*RADIATOR ASSY	Not Necessary	2,397.40 F	*- F
51	1		*COOLANT	Not Necessary	12.32 F	*- F
52	1		*AIR CON CONDENSER ASSY	Not Necessary	1,928.00 F	*- F
53	1		*LINER FR FENDER RH	Not Necessary	223.50 F	*- F
54	1		*PAD FR WHEEL RH	Not Necessary	65.00 F	*- F
55	1		*LINER FR FENDER LH	Not Necessary	219.10 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
56	1		*LINER FR FENDER LH	Not Necessary	219.10 F	*- F	
57	1		*LINER FR FENDER RH	Not Necessary	223.50 F	*- F	
58	1		*SUPPORT RADIATOR UPPER RH	Repair	85.20 F	*- F	
					Total Parts (\$)	23,889.42	6,282.47

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	1,354.00	650.00
3	TOWING CHARGE	New	56.00	56.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
6	TO APPLY RUST PROOFING ON AFFECTED AREA	New	200.00	20.00
7	TO TOP UP A/C GAS	New	120.00	0.00
8	TO CONDUCT RADIATOR PRESSURE CHECK	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
			Gross Labour Cost (\$\$)	3,144.00
				1,256.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >