

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunoss Road 8, #09-04A Singapore Post Centre  
Singapore 408600

Our File No: CS/ICS24110561/TQP3M4  
Date: 13/02/2025

REFERENCE

Insured/Claimant:	HARIZ MUHAMAD SYAHMI	Policy No:	MPC24P00285500	
Date of Loss:	24/11/2024	Nature of Claim:	OD	Claim No: DMPC2401616H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1974E		
Make & Model:	BMW X3 XDRIVE30I, 2.0 LED NAV HUD MSPT (A)	Engine No:	H3883309B48B20B
Reg. Date:	26/07/2019 (Man. Year: 2019)	Chassis No:	WBATR92030LE27126
Colour:	Grey	Odometer:	138881 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R20	Rear Tyre Size:	245/45R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm
The above values represent the remaining tyre treads depth			

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,009.50	13,183.50	12,826.00	49.31
Miscellaneous Items	55.00	55.00	0.00	0.00
Labour	1,420.00	1,000.00	420.00	29.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,484.50	14,238.50	13,246.00	48.19
Approved Total (Overridden) (S\$)		11,400.00		
- Excess (S\$)	500.00	0.00	500.00	100.00
(S\$)	26,984.50	11,400.00	15,584.50	57.75
+ GST 9.00/9.00% (S\$)	2,428.61	1,026.00	1,402.61	57.75
Nett Amount (S\$)	29,413.11	12,426.00	16,987.11	57.75

INSPECTION

Date of Assignment:	27/11/2024 Present Location:	CYS Automobile Services Pte Ltd (Woodlands) CYS AUTOMOBILE SERVICES PTE LTD (WOODLANDS)
Date Inspected:	27/11/2024 Inspected At:	38 WOODLANDS INDUSTRIAL PARK EAST 1, #07-17, ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2025)
Parts:	M1-SUV	BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1974E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	2,200.00 F	*1,950.00 F
2	1		*BONNET EMBLEM (WCP)	Necessary	85.00 F	*85.00 F
3	2		*BONNET LOCK (WCP)	Not Necessary	260.00 F	*- F
4	1		*BONNET LOCK PASSIVE WITH SWITCH (WCP)	Not Necessary	90.00 F	*- F
5	1		*FRONT GRILLE BASE (WCP)	Cracked	390.00 F	*390.00 F
6	2		*FRONT GRILLE CHROME (WCP)	Cut	280.00 F	*280.00 F
7	1		*FRONT GRILLE AIR FLAP CONTROL (WCP)	Distorted	120.00 F	*120.00 F
8	1		*FRONT BUMPER (WCP)	Deformed	1,800.00 F	*1,600.00 F
9	1		*FRONT BUMPER REINFORCEMENT UPPER (WCP)	Bent	980.00 F	*980.00 F
10	1		*FRONT BUMPER REINFORCEMENT LOWER (WCP)	Not Necessary	420.00 F	*- F
11	1		*FRONT BUMPER SPONGE (WCP)	Not Necessary	90.00 F	*- F
12	2		*FRONT BUMPER FOG LAMP (WCP)	Not Necessary	1,100.00 F	*- F
13	2		*FRONT BUMPER FOG LAMP GARNISH (WCP)	Not Necessary	280.00 F	*- F
14	1		*FRONT BUMPER CENTRE GARNISH (WCP)	Deformed	250.00 F	*250.00 F
15	1		*FRONT BUMPER NUMBER PLATE GARNISH (WCP)	Deformed	110.00 F	*110.00 F
16	1		*FRONT BUMPER TOWING COVER (WCP)	Missing	60.00 F	*60.00 F
17	1		*FRONT BUMPER CAMERA (WCP)	Distorted	780.00 F	*580.00 F
18	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	190.00 F	*190.00 F
19	1		*FRONT BUMPER PARKING SENSOR 3PCS (WCP)	Not Working (2Pcs Only)	1,440.00 F	*960.00 F
20	2		*FRONT BUMPER PARKING SENSOR BRACKET (WCP)	Necessary	300.00 F	*150.00 F
21	1		*FRONT SUPPORT PANEL (WCP)	Not Necessary	350.00 F	*- F
22	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Cracked	280.00 F	*280.00 F
23	1		*AIR-CON CONDENSER (WCP)	Not Necessary	1,190.00 F	*- F
24	1		*RADIATOR 1 (WCP)	Not Necessary	850.00 F	*- F
25	1		*RADIATOR 2 (WCP)	Not Necessary	750.00 F	*- F
Supplementary #1						
26	1		*HEADLAMP ASY (WCP)	O/S Cracked/ N/S Not Necessary	9,000.00 F	*4,000.00 F

F=Franchise part.

Sub Total (S\$) 23,645.00 11,985.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>					2,364.50	1,198.50
<b>Total Parts (S\$)</b>					<b>26,009.50</b>	<b>13,183.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	4	FRONT BUMPER CLIPS Necessary	20.00	20.00
2	1	FRONT NUMBER PLATE Bent	35.00	35.00
<b>Sub Total (\$\$)</b>			<b>55.00</b>	<b>55.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REFIX FRONT PARKING SENSOR & CHECK WIRING FUNCTION	New	50.00	50.00
2	TO REMOVE AIR-CON CONDENSER, PIPE, DRIER & TOP-UP AIR-CON GAS	New	120.00	0.00
3	LABOUR CHARGE FOR REMOVING, REFITTING AND REPAIRING OF AFFECTED ACCIDENT PARTS	New	650.00	450.00
4	TO PUTTY AND SPRAY PAINTING CHARGES	New	600.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,420.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >