

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110565/UQP3E2
Date: 09/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	FBS2246X	Insured Vehicle No :	SLQ4318B
Date of Loss:	10/11/2024	Nature of Claim:	TP
		Claim No:	DMCF2400103H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS2246X	Engine No:	KF61E1024116
Make & Model:	HONDA ADV150, 149cc ABS CVT	Chassis No:	MH1KF6118LK023983
Reg. Date:	23/02/2021 (Man. Year: 2020)	Odometer:	75157 km
Colour:	White		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120-70-14	Rear Tyre Size:	130-70-13
Front Left Side:	IRC 7 mm	Rear Left Side:	IRC 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,775.80	2,559.80	216.00	7.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	325.00	250.00	75.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,100.80	2,809.80	291.00	9.38
Approved Total (Overridden) (S\$)		2,200.00		
	(S\$)	3,100.80	2,200.00	900.80
	+ GST 9.00/9.00% (S\$)	279.07	198.00	81.07
	Nett Amount (S\$)	3,379.87	2,398.00	981.87

INSPECTION

Date of Assignment:	26/11/2024	
Date Inspected:	27/11/2024	Inspected At: Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 Singapore 539187
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Dec 2024)	
Parts:	N/A	HONDA ADV150 149cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS2246X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER MUFFLER	Cut	45.00 FL	*45.00 FL
2	1		*PROTECTOR MUFFLER	Cut	165.00 FL	*165.00 FL
3	1		*FORK ASSY LH	Serviceable	185.00 FL	*- FL
4	1		*FRONT BRAKE LEVER	Cut	25.00 FL	*25.00 FL
5	1		*HANDLE BAR	Bent	75.00 FL	*75.00 FL
6	1		*FRONT CENTER COVER	Cracked	95.00 FL	*95.00 FL
7	1		*FRONT SIDE COVER RH	Cracked	195.00 FL	*195.00 FL
8	1		*COVER FLOOR SIDE RH	Cracked	98.00 FL	*98.00 FL
9	1		*STEP FLOOR RH	Cut	75.00 FL	*75.00 FL
10	1		*COVER FLOOR SIDE LH	Cut	98.00 FL	*98.00 FL
11	1		*STEP FLOOR LH	Cut	75.00 FL	*75.00 FL
12	1		*FRONT FENDER	Cracked	110.00 FL	*110.00 FL
13	1		*COVER OUTER AIR CLEANER	Cut	55.00 FL	*55.00 FL
14	1		*CASE INNER AIR CLEANER	Not Necessary	55.00 FL	*- FL
15	1		*FRONT SIGNAL RH	Cracked	65.00 FL	*65.00 FL
16	1		*MIRROR RH	Cut	35.00 FL	*35.00 FL
17	1		*CAP TAIL	Cracked	35.00 FL	*35.00 FL
18	1		*COVER REAR UPPER FENDER	Distorted	40.00 FL	*40.00 FL
19	1		*BRACKET REAR FENDER	Distorted	75.00 FL	*75.00 FL
20	1		*COVER REAR FENDER LOWER	Distorted	38.00 FL	*38.00 FL
21	1		*FENDER A	Distorted	60.00 FL	*60.00 FL
22	1		*REFLECTOR	Broken	20.00 FL	*20.00 FL
23	1		*REAR FENDER C	Distorted	48.00 FL	*48.00 FL
24	1		*FRONT LOWER COVER	Cut	60.00 FL	*60.00 FL
25	1		*FRONT SIDE COVER LH	Cut	195.00 FL	*195.00 FL
26	1		*HEAD LAMP ASSY	Cracked	800.00 FL	*800.00 FL
27	1		*STAY FRONT COVER LH	Damaged	60.00 FL	*60.00 FL
28	1		*STAY FRONT COVER RH	Damaged	60.00 FL	*60.00 FL
29	1		*HEADLIGHT COVER	Cut	55.00 FL	*55.00 FL
30	1		*NUMBER PLATE LIGHT	Cracked	65.00 FL	*65.00 FL
31	1		*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,082.00	2,842.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	306.20	282.20
Total Parts (\$\$)	2,775.80	2,559.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT (REFER TO LOD)	New	45.00	0.00
2	LABOUR CHARGES	New	280.00	250.00
			Gross Labour Cost (\$)	325.00
				250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >