



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNF 5995Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	MTG CRACKED	\$850.70	\$720.10
1	REAR O/S BUMPER SIDE GARNISH	DISTORTED	\$305.10	\$305.10
1	REAR O/S BUMPER SIDE RETAINER	CRACKED	\$65.70	\$65.70
1	REAR O/S BUMPER REFLECTOR	SERVICEABLE	\$155.60	\$0.00
1	REAR O/S REVERSE SENSOR	SERVICEABLE	\$255.70	\$0.00
	LESS 25.00% DISCOUNT		(\$408.20)	(\$272.73)
			\$1,224.60	\$818.17

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIP @\$2.00 (SN)	NECESSARY	\$20.00	\$20.00
			\$20.00	\$20.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING		\$600.00	\$200.00
	TO PUTTY AND SPRAY PAINT		\$600.00	\$200.00
	CHECK & RECONNECT WIRING		\$35.00	\$10.00
			\$1,235.00	\$410.00

GRAND TOTAL			\$2,479.60	\$1,248.17
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,000.00

Report Ref No: CS/SPF24110566/Kqp3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$1,100

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.