



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2500078

INV Date 06/01/2025

Reference CD/LPC24110569/Kma3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SDV 8811K

Insured Veh. GBL 8086M

Claim No. 24/24/24/VC05/030248

Policy No.

Accident Date 20/11/2024

Inspection Date 28/11/2024

Description	Total
Survey Inspection	300.00
Digital Photographs	
Transportation	
Subtotal	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110569/Kma3q2(N)	
			Date: 06/01/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 8086M	Veh. Inspected	SDV 8811K
	Policy No.		Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030248	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	28/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2023
	Chassis No.	MR2BE3BE200021560	Colour	METALLIC PEARL WHITE
	Odometer	30200 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	7 mm
	L/H Front Tyre	225/45 R17	MICHELIN	7 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	7 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/11/2024	Inspection Date	28/11/2024
	Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 8811K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT GRILLE ASSY	* CHECK	432.60	-
1	FRONT GRILLE BASE	* CHECK	261.60	-
1	FRONT BUMPER	* CHECK	565.70	-
15	FRONT BUMPER CLIPS	NECESSARY	57.00	57.00
1	FRONT BUMPER LOWER AIR GRILLE	CRACKED	511.60	511.60
1	FRONT BUMPER REINFORCEMENT	* CHECK	663.50	-
1	FRONT BUMPER SPONGE	* CHECK	125.30	-
	LESS 25% DISCOUNT		-654.33	-142.15
			1,962.97	426.45
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	DENTED	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD .TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.		300.00	200.00
	TO SPRAY FRONT BUMPER .		300.00	200.00
			600.00	400.00
	GRAND TOTAL		2,597.97	861.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,536.53 NETT)			680.00

Report Ref No. CD/LPC24110569/Kma3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SDV 8811K



PHOTOGRAPHS FOR VEHICLE NO. : SDV 8811K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SDV 8811K

