



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: JOANNE YONG			Ref: CS/FCI24110571/Knp3m4(N) Date: 26/02/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 6666Z	Veh. Inspected	GBB 7652M
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24010250MFCT	Excess (\$)	0.00
	Assign From	SWEE KEONG	Assign Date	26/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	NISSAN URVAN (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JN1MG4E25Z0793174	Colour	METALLIC GREY
	Odometer	281746 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	R/H Rear Tyre	195 R15X8	BRIDGESTONE	7 mm
	L/H Rear Tyre	195 R15X8	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/11/2024	Inspection Date	27/11/2024
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	