



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: HARMINDER			Ref: CS/FCI24110573/RUvp3m4 (N) Date: 18/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 1201E	Veh. Inspected	SDV 9099T
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24010371MFCT	Excess (\$)	0.00
	Assign From	HARMINDER	Assign Date	27/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	W1N2539802F979813	Colour	BLACK
	Odometer	54328 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60R18	PIRELLI	6 mm
	L/H Front Tyre	235/60R18	PIRELLI	6 mm
	R/H Rear Tyre	235/60R18	PIRELLI	6 mm
	L/H Rear Tyre	235/60R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/11/2024	Inspection Date	29/11/2024
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	