

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110577/APA3Q2
Date: 28/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_04
Claimant Vehicle No : SNN4920D Insured Vehicle No : SMM9272A
Date of Loss: 26/11/2024 Nature of Claim: TP Claim No: MFL2024D0014123

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNN4920D
Make & Model: HONDA VEZEL, 1.5 G CVT (A) Engine No: L15Z1006730
Reg. Date: 12/12/2023 (Man. Year: 2022) Chassis No: RV31005777
Colour: Gold Odometer: 81845 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------|------------|------------|--------|
| Parts | 3,364.08 | 2,105.44 | 1,258.64 | 37.41 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,010.00 | 480.00 | 530.00 | 52.48 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,374.08 | 2,585.44 | 1,788.64 | 40.89 |
| Approved Total (Overridden) (S\$) | | 2,000.00 | | |
| (S\$) | 4,374.08 | 2,000.00 | 2,374.08 | 54.28 |
| + GST 9.00/9.00% (S\$) | 393.67 | 180.00 | 213.67 | 54.28 |
| Nett Amount (S\$) | 4,767.75 | 2,180.00 | 2,587.75 | 54.28 |
| + Car Rental (3.0 x S\$100.00/day) (S\$) | | 300.00 | | |
| + Doc/Search Fee (S\$) | | 27.25 | | |
| Nett Liability (S\$) | | 2,507.25 | | |

INSPECTION

Date of Assignment: 27/11/2024
Date Inspected: 27/11/2024 Inspected At: Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT
AUTOHUB
Singapore 417921
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Feb 2025) |
| Parts: | 144 | HONDA VEZEL 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNN4920D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|--|--|
| 1 | 1 | | *REAR AXLE | Bent | 1,407.70 FL | *1,407.70 FL |
| 2 | 1 | | *REAR RH BEARING WITH SENSOR | Damaged | 397.60 FL | *397.60 FL |
| 3 | 1 | | *REAR RH FENDER ARCH GARNISH | Cut | 201.50 FL | *201.50 FL |
| 4 | 1 | | *REAR RH FENDER INNER SHIELD COVER | Not Necessary | 197.50 FL | *- FL |
| 5 | 1 | | *REAR RH SHOCK ABSORBER | Not Necessary | 475.60 FL | *- FL |
| 6 | 1 | | *REAR RH SPORT RIM | Cut | 780.16 FS | *480.00 FS |
| 7 | 1 | | *SET REAR RH FENDER ARCH GARNISH CLIPS | Necessary | 30.00 FS | *20.00 FS |
| 8 | 1 | | *REAR RH TYRE | Not Necessary | 380.00 FS | *- FS |
| 9 | 1 | | *SET REAR RH FENDER INNER SHIELD COVER CLIPS | Not Necessary | 30.00 FS | *- FS |
| | | | | | | F=Franchise part. S=SpcNett. L=ListItemDisc. |
| | | | | | Sub Total (S\$) | 3,900.06 2,506.80 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (S\$) | 535.98 401.36 |
| | | | | | Total Parts (S\$) | 3,364.08 2,105.44 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE, CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC | New | 450.00 | 300.00 |
| 2 | TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM | New | 100.00 | 80.00 |
| 3 | TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT | New | 400.00 | 100.00 |
| 4 | TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL | New | 60.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,010.00 | 480.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >