

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|------------------------------------|---|---|----------------|---------|--------------------------|--|
| | INCOME INSURAN | ICE LTD | | Ref: | CS/INC24110578/Anh3e2(N) | |
| | 75 BRAS BASAH FINCOME CENTRE | ROAD SINGAPORE 189557 | | Date: | 11/03/2025 | |
| | ATTN: JULIE | | | Code: | INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHC 5731E | Veh. Inspecte | d | SMH 9062R | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1305644-002 | Excess (\$) | | 0.00 | |
| | Assign From | ANNIE KOH | Assign Date | | 27/11/2024 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA VIOS | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | MR2B23F3201164956 | Colour | | RED | |
| | Odometer | 106858 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 185/60 R15 | MICHELIN | | 6 mm | |
| | L/H Front Tyre | 185/60 R15 | MICHELIN | | 6 mm | |
| | R/H Rear Tyre | 185/60 R15 | MICHELIN | | 6 mm | |
| | L/H Rear Tyre | 185/60 R15 | MICHELIN | | 6 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| | | | | | 10 | |
| 5. | 5. General Information | | | | | |
| | Accident Date | 24/11/2024 | Inspect Date / | Time | 27/11/2024 (06:07 PM) | |
| | Survey held at | KT MOTORWERK | | | | |
| | - | 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 | | | | |
| 5a. | . Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | | 7 Worki | ng Days | |