



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBL 982D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER	CRACKED	\$280.00	\$160.00
2	FORK INNER TUBES	SERVICEABLE	\$640.00	\$0.00
2	FORK OUTER TUBES	NOT NECESSARY	\$660.00	\$0.00
1	FORK UNDER BRACKET	NOT NECESSARY	\$280.00	\$0.00
1	FRONT RIM	SERVICEABLE	\$580.00	\$0.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$285.00	\$0.00
1	FRONT RIM SHAFT	CUT	\$125.00	\$60.00
1	FRONT RIM BEARING	NOT NECESSARY	\$88.00	\$0.00
2	FRONT SIGNAL	N/S CRACKED	\$280.00	\$110.00
2	SIDE MIRROR - R/L	BROKEN	\$160.00	\$90.00
1	HANDLE BAR	BENT	\$285.00	\$285.00
1	HANDLE BAR BALANCER	CUT	\$105.00	\$50.00
1	SET HAND GRIP	TORN	\$90.00	\$70.00
1	CLUTCH LEVER	CUT	\$125.00	\$110.00
2	FUEL TANK SIDE COVER - R/L	N/S CRACKED	\$600.00	\$290.00
2	FRONT FOOTREST	N/S BROKEN	\$180.00	\$90.00
2	FRONT FOOTREST BRACKETS	NOT NECESSARY	\$380.00	\$0.00
2	REAR FOOTREST	N/S CRACKED	\$140.00	\$70.00
2	REAR FOOTREST BRACKET	N/S BENT	\$280.00	\$140.00
2	REAR TAIL BOARD	CRACKED	\$560.00	\$400.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	\$950.00	\$0.00
1	EXHAUST END CAP	CUT	\$115.00	\$60.00
1	EXHAUST PROTECTOR	CUT	\$145.00	\$145.00
	<b>LESS 10.00% DISCOUNT</b>		(\$733.30)	(\$213.00)
			<b>\$6,599.70</b>	<b>\$1,917.00</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR NUMBER PLATE (SN)	BENT	\$38.00	\$20.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	\$95.00	\$0.00
1	REAR BOX (SN)	CUT	\$480.00	\$380.00
1	REAR BOX BRACKET (SN)	BENT	\$180.00	\$150.00
			\$879.00	\$550.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY		\$480.00	\$300.00
			\$980.00	\$300.00
<b>GRAND TOTAL</b>			<b>\$8,458.70</b>	<b>\$2,767.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$1,700.00</b>
Report Ref No: CS/INC24110582/Unh3e2				

TOTAL FOR SPARE PARTS: \$ 7,478.70 \$ 2,467.00  
TOTAL FOR LABOUR : \$ 980.00 \$ 300.00  
TOTAL REPAIR COST: \$ 8,458.70 \$ 2,767.00

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.