

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURANCE LTD			Ref:	CS/INC24110585/Avh3e2(N)	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	29/09/2025	
	ATTN: YEE PEI LI			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKE 5475Z	Veh. Inspected	k	SJZ 1019K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1305693-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		26/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO FORTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	KNAFW411MA5271549	Colour		WHITE	
	Odometer	146877 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	MICHELIN		6 mm	
	L/H Front Tyre	225/45 R17	MICHELIN		6 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN		6 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
	DAMAGES SEE DE	=TAILS.				
_						
5. General Information						
	Accident Date	24/11/2024	Inspect Date /	Time	27/11/2024 (03:30 PM)	
	Survey held at	Survey held at HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				