



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 238C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT RH FENDER	BENT	1,552.00	1,162.00
1	FRONT RH DOOR	BENT / WARPED	2,771.00	2,771.00
1	FRONT RH DOOR PILLAR OUTER GARNISH	SERVICEABLE	194.00	-
1	RH DOOR SIDE SKIRT CHROME TRIMMING	DENTED	278.00	278.00
	LESS 10% DISCOUNT		-479.50	-421.10
			4,315.50	3,789.90
1	FRONT RH DOOR WEATHER STRIP (SN) (50%)	NECESSARY	444.00	222.00
	LESS 10% DISCOUNT		-44.40	-
			399.60	222.00
	<b><u>LABOUR</u></b>			
	REMOVE AND REFIT FRONT RH DOOR, FRONT RH DOOR PILLAR OUTER GARNISH, FRONT RH DOOR WEATHER STRIP, RH DOOR SIDE SKIRT CHROME TRIMMING. }		900.00	450.00
	REMOVE & REFIT FRONT BUMPER. }		-	-
	REMOVE AND REFIT FRONT RH FENDER. }		-	-
	REMOVE & TRANSFER FRONT RH DOOR NECESSARY ATTACHMENT SPARE PARTS ITEM. }		-	-
	PUTTY / PRIMER APPLICATION, SPRAY PAINTING FRONT RH FENDER, FRONT RH DOOR.		500.00	500.00
			1,400.00	950.00
	<b>GRAND TOTAL</b>		<b>6,115.10</b>	<b>4,961.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,100.00</b>

Report Ref No. CS/LIP24110592/Kvh3e2(N)

MARKET VALUE: \$114,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$59,838.00=NETT VALUE: \$54,162.00

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.