

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110593/KNP3E2
Date: 13/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MCV24A00054700
Claimant Vehicle No :	SJX7963E	Insured Vehicle No :	GBF5339K
Date of Loss:	25/11/2024	Nature of Claim:	TP
		Claim No:	DMCV2400264H/03/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX7963E	Engine No:	G4FCAU848739
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BMAU020201
Reg. Date:	13/07/2010 (Man. Year: 2010)	Odometer:	182218 km
Colour:	Metallic Maroon		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,505.60	5,438.00	3,067.60	36.07
Miscellaneous Items	380.00	296.00	84.00	22.11
Labour	3,870.00	1,790.00	2,080.00	53.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,755.60	7,524.00	5,231.60	41.01
Approved Total (Overridden) (\$\$)		5,900.00		
(\$\$)	12,755.60	5,900.00	6,855.60	53.75
+ GST 9.00/9.00% (\$\$)	1,148.00	531.00	617.00	53.75
Nett Amount (\$\$)	13,903.60	6,431.00	7,472.60	53.75

INSPECTION

Date of Assignment:	27/11/2024	Present Location:	Accord Auto Services Pte Ltd (HQ)
Date Inspected:	28/11/2024	Inspected At:	Accord Auto Services Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days		10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2024)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX7963E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR (WCP)	Repair	1,090.00 F	*- F
2	1		*FRONT RH DOOR OUTER MOUNDLING (WCP)	Serviceable	45.00 F	*- F
3	1		*FRONT RH DOOR RUBBER @ DOOR (WCP)	Serviceable	106.00 F	*- F
4	1		*FRONT RH DOOR RUBBER @ BODY (WCP)	Serviceable	97.00 F	*- F
5	1		*FRONT RH FENDER (WCP)	Bent	440.00 F	*440.00 F
6	1		*FRONT RH FENDER INNER SHIELD (WCP)	Cracked	57.00 F	*57.00 F
7	1		*FRONT BUMPER (WCP)	Cracked	435.00 F	*435.00 F
8	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Cracked	22.00 F	*22.00 F
9	1		*FRONT HEADLAMP RH (WCP)	Missing	480.00 F	*480.00 F
10	1		*FRONT HEADLAMP LOWER BRACKET (WCP)	Cracked	790.00 F	*790.00 F
11	1		*FRONT SHOCK ABSORBER RH (WCP)	Bent	234.00 F	*234.00 F
12	1		*FRONT KUNCKLE RH (WCP)	Bent	309.00 F	*309.00 F
13	1		*FRONT LOWER ARM RH (WCP)	Distorted	282.00 F	*282.00 F
14	1		*FRONT STABILIZER LINKAGE RH (WCP)	Serviceable	200.00 F	*- F
15	1		*FRONT TIE ROD RH (WCP)	Serviceable	95.00 F	*- F
16	1		*FRONT RACK END RH (WCP)	Serviceable	55.00 F	*- F
17	1		*FRONT WHEEL BEARING RH (WCP)	Necessary	124.00 F	*124.00 F
18	1		*FRONT BONNET (WCP)	Bent	1,067.00 F	*1,067.00 F
19	2		*FRONT BONNET HINGE (WCP)	Repair	260.00 F	*- F
20	1		*RIM	Dented	900.00 F	*350.00 FS
					Sub Total (S\$)	7,088.00 4,590.00
					+ Margin on L,N Items 20.00/20.00% (S\$)	1,417.60 848.00
					Total Parts (S\$)	8,505.60 5,438.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	FRONT FENDER INNER SHIELD CLIPS (NECESSARY)	50.00	50.00
3	1	TYRE (TORN)(70%)	280.00	196.00
Sub Total (\$\$)			380.00	296.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,500.00	800.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00	650.00
3	TO CHECK WIRING SYSTEM	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	60.00
5	WHEEL ALIGNMENT	New	150.00	60.00
6	TO REMOVE/REFIX/REPLACE UNDERCARRIAGE	New	350.00	200.00
7	TO REMOVE/REPLACE/REFIX FRONT RH DOOR WINDOW GLASS, MECHANISM & ETC TO NEW DOOR	New	150.00	0.00
Gross Labour Cost (\$\$)			3,870.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >