

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24110595/UVP3M4**Date:** 18/03/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002279692
<b>Claimant Vehicle No :</b>	XD8779D	<b>Insured Vehicle No :</b>	SKN129J
Date of Loss:	19/11/2024	Nature of Claim:	TP
		Claim No:	382279

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>XD8779D</b>	Engine No:	6UZ1484141
Make & Model:	ISUZU FXZ77M, 9.8 D (M)	Chassis No:	JALFXZ77ME7000040
Reg. Date:	07/05/2014 (Man. Year: 2014)	Odometer:	601471 km
Colour:	Green/Blue		
Engine Capacity:	9839 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	MAX WIND 7 mm	Rear Left Side:	MAX WIND 7/7/7/7 mm
Front Right Side:	MAX WIND 7 mm	Rear Right Side:	MAX WIND 7/7/7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	90,000.00	45,000.00	45,000.00	50.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	800.00	1,200.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>92,000.00</b>	<b>45,800.00</b>	<b>46,200.00</b>	<b>50.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>34,000.00</b>		
<b>(S\$)</b>	92,000.00	34,000.00	58,000.00	63.04
<b>+ GST 9.00/9.00% (S\$)</b>	8,280.00	3,060.00	5,220.00	63.04
<b>Nett Amount (S\$)</b>	<b>100,280.00</b>	<b>37,060.00</b>	<b>63,220.00</b>	<b>63.04</b>

INSPECTION

Date of Assignment:	28/11/2024	
Date Inspected:	03/12/2024	Inspected At:
Estimated Period of Repair:	3.0 days	
		HUP LIAN HUAT ENGINEERING WORKS 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, SINGAPORE 539278

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Mar 2025)	
Parts:	N/A	ISUZU FXZ77M 9.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8779D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TMA ASSY SECTION I (INNER)	Distorted	45,000.00 FS	*45,000.00 FS
2	1		*TMA ASSY SECTION II (OUTER)	Repair	45,000.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	
					90,000.00	45,000.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE TMA ASSY SECTION I RENEW & REFIT BACK }	New	1,000.00	800.00
2	LABOUR TO DISMANTLE TMA ASSY SECTION II RENEW & REFIT BACK }	New	1,000.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >