



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2503853

INV Date 19/06/2025

Reference CD/LPC24110597/Tma3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBD 5503M
Insured Veh. YQ 2092K
Claim No. 24/24/24/VC05/030175
Policy No. Z24VC05021665
Accident Date 11/11/2024
Inspection Date 05/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110597/Tma3q2(N)	
			Date: 19/06/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 2092K	Veh. Inspected	GBD 5503M
	Policy No.	Z24VC05021665	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030175	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	05/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTFAT35Y70K203796	Colour	WHITE
	Odometer	394591 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	FORTUNE	6 mm
	L/H Front Tyre	195 R15	FORTUNE	6 mm
	R/H Rear Tyre	155 R12	FORTUNE	6 mm
	L/H Rear Tyre	155 R12	FORTUNE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2024	Inspection Date	05/12/2024
	Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 5503M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILAMP ASSY LH	CRACKED	160.00	160.00
1	TAILAMP ASSY RH	CRACKED	160.00	160.00
	LESS 25% DISCOUNT		-80.00	-80.00
			240.00	240.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR METAL DROPSIDE W/ALUMINIUM CHEQUER PLATE (SN)	BENT	650.00	650.00
2	L-LOCKING DEVICE FOR DROPSIDE ,LH & RH @\$45.00 (SN)	BENT	90.00	90.00
1	STICKER 70KM/H (SN)	NECESSARY	10.00	10.00
1	STICKER 6 PAX (SN)	NECESSARY	12.00	12.00
1	STICKER TOYOTA (SN)	NECESSARY	80.00	80.00
1	STICKER DYNA (SN)	NECESSARY	40.00	40.00
1	REVERSE BUZZER (SN)	NOT WORKING	120.00	120.00
1	REAR EMBOSS NUMBER PLATE (SN)	BENT	40.00	30.00
			1,042.00	1,032.00
<u>LABOUR</u>				
	TO JACK ,KNOCK AND STRAIGHTEN METAL DECK REAR LOWER FRAME .REMOVE AND REPLACE DAMAGED PARTS AS ABOVE ,CHECK AND RECONNECT TAILAMP & REVERSE BUZZER WIRING ETC.		1,250.00	700.00
	SPRAY PAINTING.		400.00	300.00
			1,650.00	1,000.00
GRAND TOTAL			2,932.00	2,272.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CD/LPC24110597/Tma3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 14 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M



PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

REINSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 5503M

