



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN

Ref: CS/INC24110598/Anh3e2(N)

Date: 21/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 7619B	Veh. Inspected	GBK 2444H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1304411-002	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	28/11/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE DX	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GDH2012009535	Colour	GREEN
Odometer	194159 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/11/2024	Inspect Date / Time	05/12/2024 (02:06 PM)
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**