

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110599/EVP3E2
Date: 14/01/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNA688U	Insured Vehicle No :	GBF5339K
Date of Loss:	25/11/2024	Nature of Claim:	TP
		Claim No:	DMCV2400264H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA688U	Engine No:	DEM028295
Make & Model:	AUDI A5, 2.0 (A)	Chassis No:	WAUZZZF53MA016761
Reg. Date:	26/02/2021 (Man. Year: 2020)	Odometer:	49517 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,285.20	8,556.60	11,728.60	57.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	1,560.00	3,260.00	67.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,105.20	10,116.60	14,988.60	59.70
Approved Total (Overridden) (\$\$)		8,100.00		
(\$\$)	25,105.20	8,100.00	17,005.20	67.74
+ GST 9.00/9.00% (\$\$)	2,259.47	729.00	1,530.47	67.74
Nett Amount (\$\$)	27,364.67	8,829.00	18,535.67	67.74

INSPECTION

Date of Assignment:	28/11/2024	
Date Inspected:	28/11/2024	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2025)
Parts:	M1-COUPE	AUDI A5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA688U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	3,012.00 FL	*2,945.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Broken	45.00 FL	*45.00 FL
4	1		*REAR BUMPER LOWER SPOILER	Not Necessary	837.00 FL	*- FL
5	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	267.00 FL	*- FL
6	1		*REAR BUMPER LH SIDE CORNER REVERSE SENSOR	Not Necessary	267.00 FL	*- FL
7	6		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	24.00 FL	*24.00 FL
8	6		*REAR BUMPER REVERSE SENSOR HOLDERS	Not Necessary	154.00 FL	*- FL
9	1		*LH TAILLAMP ASSY	Broken / Cut	1,381.00 FL	*1,381.00 FL
10	1		*LH TAILLAMP PANEL	Not Necessary	156.00 FL	*- FL
11	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	60.00 FL	*- FL
12	1		*REAR LH FENDER	Dented	5,049.00 FL	*5,049.00 FL
13	1		*REAR LH FENDER INNER TRIM	Not Necessary	938.00 FL	*- FL
14	1		*REAR LH FENDER GLASS WITH RUBBER MOULDING	Not Necessary	773.00 FL	*- FL
15	1		*REAR LH FENDER SPLASH SHIELD	Not Necessary	289.00 FL	*- FL
16	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
17	1		*REAR LH FENDER INNER LOWER DUCT	Not Necessary	78.00 FL	*- FL
18	1		*REAR LH WHEEL BEARING	Not Necessary	708.00 FL	*- FL
19	1		*REAR LH KNUCKLE ARM	Not Necessary	2,301.00 FL	*- FL
20	1		*REAR LH LOWER ARM	Not Necessary	632.00 FL	*- FL
21	1		*REAR LH SHOCK ABSORBER	Not Necessary	528.00 FL	*- FL
22	1		*REAR LH UPPER ARM	Not Necessary	440.00 FL	*- FL
23	1		*REAR LH CONTROL ARM	Not Necessary	437.00 FL	*- FL
24	1		*REAR LH FENDER GLASS SEALANT	Necessary	75.00 FS	*30.00 FS
25	1		*REAR LH FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS
26	1		*REAR LH FENDER JOINT SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR LH SPORT RIM	Not Necessary	1,800.00 FS	*- FS
28	1		*REAR LH TYRE	Not Necessary	700.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,211.00	9,504.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	925.80	947.40
Total Parts (\$\$)	20,285.20	8,556.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,600.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,500.00	450.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	50.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS (6 SENSORS)	New	180.00	30.00
6	REMOVE AND REFIT REAR INNER GARNISH AND BOARDS TO ASSIST REPAIR	New	400.00	120.00
7	REMOVE AND REPLACE REAR LH FENDER GLASS TO ASSIST REPAIR	New	180.00	80.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	180.00	0.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	600.00	0.00
Gross Labour Cost (\$)			4,820.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >