



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBK 4479U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HANDLE BAR	NOT NECESSARY	\$95.00	\$0.00
1	BALANCE	DAMAGED	\$60.00	\$60.00
1	MIRROR	CRACKED	\$80.00	\$80.00
1	WIND SCREEN	MISSING	\$140.00	\$140.00
1	WIND SCREEN HOLDER	CUT	\$60.00	\$60.00
1	BRAKE LEVER	CUT	\$45.00	\$45.00
1	SIGNAL LIGHT RH	NOT NECESSARY	\$85.00	\$0.00
1	SIGNAL LIGHT LH	CRACKED	\$85.00	\$85.00
1	METER	NOT NECESSARY	\$480.00	\$0.00
1	HEAD LIGHT	CUT	\$380.00	\$380.00
1	HEAD LIGHT GARNISH	CUT	\$65.00	\$65.00
1	LAMP STAY	NOT NECESSARY	\$140.00	\$0.00
1	SET FORK	BENT	\$480.00	\$480.00
1	FORK LOWER CLAMP	DAMAGED	\$380.00	\$380.00
1	STEERING CONE	NECESSARY	\$140.00	\$140.00
1	RIM	CUT	\$320.00	\$320.00
1	DISC	CUT	\$120.00	\$120.00
1	BRAKE PADDLE	CUT	\$85.00	\$85.00
1	FRONT FOOTREST RH	CUT	\$85.00	\$85.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	\$850.00	\$0.00
1	EXHAUST PIPE COVER	CUT	\$65.00	\$65.00
1	LOWER PANNER RH	CUT	\$65.00	\$65.00
1	SIDE FAIRING REAR RH	CRACKED	\$85.00	\$85.00
1	END FAIRING	CRACKED	\$65.00	\$65.00
1	SIDE FAIRING REAR LH	CRACKED	\$85.00	\$85.00
1	BOX	DAMAGED	\$280.00	\$280.00
1	BOX CARRIER	CRACKED	\$180.00	\$180.00
1	CARRIER RUBBER	NOT NECESSARY	\$60.00	\$0.00
1	FRONT FOOTREST LH	NOT NECESSARY	\$85.00	\$0.00
1	SIDE FAIRING LH	CRACKED	\$125.00	\$125.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDE FAIRING GARNISH LH	CRACKED	\$85.00	\$85.00
1	GEAR PADDLE	NOT NECESSARY	\$85.00	\$0.00
1	SIDE STAND	NOT NECESSARY	\$95.00	\$0.00
1	REAR MUDGUARD	TORN	\$110.00	\$110.00
1	FRONT MUDGUARD	CRACKED	\$120.00	\$120.00
1	TANK	DENTED	\$650.00	\$650.00
1	IU UNIT	NOT NECESSARY	\$250.00	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$444.00)
			\$6,665.00	\$3,996.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NECESSARY	\$60.00	\$30.00
			\$60.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	BODY FRAME REPAIR	NOT NECESSARY	\$480.00	\$0.00
	BODY FRAME RESPRAY		\$180.00	\$150.00
	LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST PIPE		\$680.00	\$380.00
	TOWING		\$50.00	\$50.00
			\$1,390.00	\$580.00
GRAND TOTAL			\$8,115.00	\$4,606.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,600.00
Report Ref No: CS/FCI24060304/Avh3				

MARKET VALUE: \$7,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$713.00=NETT VALUE: \$6,287.00

LWP

ADRIAN LING WAI PING



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.