

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: Date: Code:	CS/FCI24060304/Avh3 03/10/2024 FCI2
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHC 3578U	Veh. Inspected	FBK 4479U
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24005471MFCT	Excess	\$0.00
	Assign From	JOANNE TAN	Assign Date	28/06/2024
<b>2. Vehicle Details</b>				
	Make & Model	HONDA CB400X	C.C	399
	Engine No.	NC47E5000417	Year of Reg.	02/09/2015
	Chassis No.	JH2NC4798EK000422	Colour	BLACK
	Odometer	- KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance (mm)
	R/H Front Tyre	120/70R17	MICHELIN	6
	L/H Front Tyre			
	R/H Rear Tyre	160/60R17	MICHELIN	6
	L/H Rear Tyre			
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	Accident Date	20/06/2024	Inspection Date	28/06/2024
	Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				