3/12/25, 4:48 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24110600/AQP3M4

Date: 12/03/2025

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle No:

SKT4886Z

Insured Vehicle No: GBL9654S

Date of Loss: 23/11/2024 Nature of Claim: TP Claim No: DMCF2400118H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKT4886Z Reg No:

Make & Model: NISSAN SYLPHY, 1.6 CVT (A) Engine No: HR16941952C

30/07/2020 (Man. Year: 2019) Chassis No: Reg. Date: MNTBBAB17Z0035578

48331 km Colour: White Odometer:

Engine Capacity: 1598 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,982.38	4,000.00	6,982.38	63.58
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,840.00	1,870.00	2,970.00	61.36
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	15,822.38	5,870.00	9,952.38	62.90
	Approved Total (Overridden) (S\$)		4,700.00		
	Nett Amount (S\$)	15,822.38	4,700.00	11,122.38	70.30

INSPECTION

Date of Assignment: 27/11/2024

KT MOTORWERK

3012 BEDOK INDUSTRIAL PARK E, #01-2020, Date Inspected: 02/12/2024 Inspected At:

BEDOK INDUSTRIAL PARK E,

SINGAPORE 489978

Estimated Period of Repair: 6.0 days

Adjuster: **ADRIAN LING** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2025)

Parts: 143 NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT4886Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1 1 2 1 3 1 4 2 5 2 6 1 7 1 8 1 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*BOOTLID *BOOTLID SMART KEY ANTENNA *BOOTLID OUTER CHROME GARNISH *BOOTLID LAMPS *BOOTLID NUMBER PLATE LAMPS	Buckled Not Necessary Not Necessary	1,345.20 FN	*951.00 FN
3 1 4 2 5 2 6 1 7 1 8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*BOOTLID OUTER CHROME GARNISH *BOOTLID LAMPS	•	400 70 51	
4 2 5 2 6 1 7 1 8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*BOOTLID LAMPS	Not Noccessory	198.70 FN	*- FN
5 2 6 1 7 1 8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1		NOT Necessary	348.60 FN	*- FN
6 1 7 1 8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*BOOTLID NUMBER PLATE LAMPS	Not Necessary	677.00 FN	*- FN
7 1 8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1		Not Necessary	171.80 FN	*- FN
8 1 9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*BOOTLID EMBLEM SYLPHY	Necessary	95.80 FN	*95.80 FN
9 1 10 1 11 1 12 2 13 1 14 1 15 2 16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*BOOTLID LOGO	Necessary	96.80 FN	*96.80 FN
10	*BOOTLID INNER TRIM	Not Necessary	305.20 FN	*- FN
11	*BOOTLID INNER LOCK	Damaged	165.90 FN	*165.90 FN
12	*BOOTLID LOWER LATCH	Not Necessary	82.70 FN	*- FN
13	*BOOTLID WEATHERSTRIP	Cut	198.60 FN	*198.60 FN
14	*BOOTLID HINGE	Not Necessary	291.60 FN	*- FN
15	*REAR BUMPER	Deformed	935.60 FN	*783.00 FN
16 1 17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*REAR BUMPER REFLECTORS WITH BRACKETS	O/S Cracked	196.40 FN	*98.20 FN
17 2 18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*REAR BUMPER RETAINERS	Not Necessary	220.40 FN	*- FN
18 2 19 2 20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*REAR BUMPER SPONGE 3PCS	Cracked (1Pc Only)	470.40 FN	*156.80 FN
19	*REAR BUMPER SUPPORT BRACKETS	Not Necessary	291.60 FN	*- FN
20 1 21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*TAILAMPS	Cracked	851.60 FN	*581.00 FN
21 1 22 1 23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*TAILAMPS INNER SEAL	Not Necessary	70.00 FN	*- FN
22	*END PANEL	Dented	756.90 FN	*592.00 FN
23 1 24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*END PANEL TOP GARNISH	Deformed	195.60 FN	*195.60 FN
24 2 25 2 26 1 27 1 28 1 29 1 30 1 31 1	*END PANEL SMART KEY SENSOR	Cracked	185.30 FN	*185.30 FN
25 2 26 1 27 1 28 1 29 1 30 1 31 1	*REAR WINDSCREEN MOULDING	Not Necessary	185.60 FN	*- FN
26 1 27 1 28 1 29 1 30 1 31 1	*REAR FENDER INNER TRIM	Not Necessary	651.60 FN	*- FN
27 1 28 1 29 1 30 1 31 1	*REAR FENDER INNER COWLING	Not Necessary	316.40 FN	*- FN
28 1 29 1 30 1 31 1	*REAR TOOL BOX SPONGE	Not Necessary	268.90 FN	*- FN
29 1 30 1 31 1	*REAR SPARE TYRE TOP BOARD	Not Necessary	398.70 FN	*- FN
30 1 31 1	*REAR SPARE TYRE PANEL	Not Necessary	785.30 FN	*- FN
31 1	*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
*	*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
32 1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
	*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
33 1	*SET REVERSE CAMERA	Not Necessary	350.00 FS	*-FS
34 2	*BOOTLID WEATHERSTRIP	Not Necessary	360.00 FS	*-FS
35 2	*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*-FS
36 2	*SET REAR FENDER INNER TRIMS	Not Necessary	60.00 FS	*-FS
37 1	JLI ILAN FENDEN INNEN INNI	Not Necessary	30.00 FS	*-FS
38 2	*SET REAR BOOT INNER TRIM CLIPS	,	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$) 12,058.20 4,410.00
- Nett Item Discount on N Items 10.00/10.00% (S\$) 1,075.82 410.00

Total Parts (S\$) 10,982.38 4,000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	700.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	80.00
4	TO REMOVE/ REFIT INTERIOR UPHOLSTERY	New	150.00	80.00
5	TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	New	150.00	0.00
6	TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMPS	New	80.00	30.00
7	TO REMOVE AND INSTALL REAR CAMERA	New	80.00	50.00
8	TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTING	New	80.00	50.00
9	TO REMOVE AND REPLACE BOOTLID MECHANISM	New	100.00	80.00
	Gross Labour	Cost (S\$)	4,840.00	1,870.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >