

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110605/KPA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900251973
Claimant Vehicle No :	SNC1000L	Insured Vehicle No :	SMQ6416B
Date of Loss:	22/09/2024	Nature of Claim:	TP
		Claim No:	8545268822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC1000L		
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Engine No:	HIDDEN
Reg. Date:	18/11/2021 (Man. Year: 2021)	Chassis No:	LRW3F7FA0MC384528
Colour:	Metallic Pearl White	Odometer:	60229 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45ZR18	Rear Tyre Size:	235/45ZR18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	972.48	739.40	233.08	23.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	850.00	650.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,472.48	1,589.40	883.08	35.72
+ GST 9.00/9.00% (S\$)	222.52	143.05	79.47	35.71
Nett Amount (S\$)	2,695.00	1,732.45	962.55	35.72
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		2,005.63		

INSPECTION

Date of Assignment:	28/11/2024	
Date Inspected:	28/11/2024 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mounting Cracked	766.00 FL	*766.00 FL
2	1		*REAR RH BUMPER RETAINER	Serviceable	7.47 FL	*- FL
3	1		*REAR REVERSE SENSOR	Serviceable	163.55 FL	*- FL
4	1		*REAR RH WHEEL RIM COVER	Serviceable	32.40 FL	*- FL
5	1		*REAR RH FENDER PANEL OUTER (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
7	1		*REAR BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,069.42	816.00
- List Item Discount on L Items 10.00/10.00% (\$)	96.94	76.60
Total Parts (\$)	972.48	739.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	New	700.00	350.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR RH FENDER PANEL & ETC.	New	600.00	440.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	New	100.00	60.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM.	New	100.00	0.00
Gross Labour Cost (\$\$)			1,500.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >