



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 502U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,850.00	-
1	REAR BUMPER CHROME	DENTED	258.00	258.00
1	REAR BUMPER DIFFUSER	SERVICEABLE	850.00	-
2	REAR BUMPER SIDE RETAINER @ \$85.00	SERVICEABLE	170.00	-
1	REAR BUMPER CENTRE BRACKET	SERVICEABLE	185.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	850.00	-
	LESS 5% DISCOUNT		-208.15	-12.90
			3,954.85	245.10
	<u>LABOUR</u>			
	SPRAY PAINTING.		800.00	250.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER REINFORCEMENT.		800.00	220.00
			1,600.00	470.00
GRAND TOTAL			5,554.85	715.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				600.00

Report Ref No. CS/AGI24110612/Knp3m4(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.