5/2/25, 11:08 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110613/APA3Q2

Date: 02/05/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100323477-12 **Claimant Vehicle**

GBJ1962R **Insured Vehicle No:** SKH3992U No:

Date of Loss: 23/11/2024 Nature of Claim: ΤP Claim No: 1772097074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1962R**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 4DR (A) Engine No: 1KD2833152

Reg. Date: 29/01/2019 (Man. Year: 2018) Chassis No: JTFHT02P400246626

Colour: Blue Odometer: 111886 km

Engine Capacity: 2982 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: Handbrake (Serviceable): Nο

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C

Front Left Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|----------------------|------------|------------|--------|
| Parts | 3,716.25 | 3,074.60 | 641.65 | 17.27 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,910.00 | 1,500.00 | 410.00 | 21.47 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,626.25 | 4,574.60 | 1,051.65 | 18.69 |
| Approved Total (Overridden) (S\$) | | 3,600.00 | | |
| Nett Amount (S\$) | 5,626.25 | 3,600.00 | 2,026.25 | 36.01 |
| + Loss of Use (5.0 x | S\$80.00/day) (S\$) | 400.00 | | |
| + Doo | c/Search Fee (S\$) | 2.18 | | |
| | Nett Liability (S\$) | 4,002.18 | | |

INSPECTION

Date of Assignment: 26/11/2024

Chin Meng Motors (HQ)

1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit Date Inspected: 26/11/2024 Inspected At:

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: **ADRIAN LING** Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|--------------------------------------|---------------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Dented | 2,120.40 FL | *2,120.40 FL |
| 2 | 1 | | *TAILGATE WEATHERSTRIP | Not Necessary | 285.60 FL | *- FL |
| 3 | 1 | | *TAILGATE INNER LOCK | Damaged | 316.50 FL | *316.50 FL |
| 4 | 1 | | *TAILGATE EMBLEM | Necessary | 32.10 FL | *32.10 FL |
| 5 | 2 | | *TAILGATE HINGE @\$85.10 | Not Necessary | 170.20 FL | *- FL |
| 6 | 2 | | *TAILGATE STOPPER @\$42.50 | Not Necessary | 85.00 FL | *- FL |
| 7 | 1 | | *REAR BUMPER | Deformed | 575.20 FL | *575.20 FL |
| 8 | 2 | | *REAR BUMPER RETAINER@\$45.30 | Not Necessary | 90.60 FL | *- FL |
| 9 | 2 | | *REAR BUMPER BRACKET @\$65.40 | Not Necessary | 130.80 FL | *- FL |
| 10 | 6 | | *REAR BUMPER CLIPS @\$4.50 | Necessary | 27.00 FL | *27.00 FL |
| 11 | 1 | | *REAR END PANEL | Dented | 425.60 FL | *425.60 FL |
| 12 | 1 | | *TAILGATE STICKER - CERTIS CISCO | Necessary | 80.00 FS | *80.00 FS |
| 13 | 1 | | *TAILGATE STICKER - CERTISGROUP.COM | Necessary | 80.00 FS | *80.00 FS |
| 14 | 1 | | *TAILGATE STICKER - TEL: 18007472888 | Necessary | 80.00 FS | *80.00 FS |
| 15 | 1 | | *TAILGATE STICKER - 70KM/H | Necessary | 12.00 FS | *12.00 FS |
| 16 | 1 | | *REAR NO PLATE | Not Necessary | 20.00 FS | *- FS |
| 17 | 1 | | *REVERSE SENSOR (4 PCS) | Damaged | 250.00 FS | *200.00 FS |
| F=Fra | inchise | part. S=SpcN | lett. L=ListItemDisc. | Ob T-4-1 (OA) | 4 704 00 | 2.242.22 |
| | | | | Sub Total (S\$) | 4,781.00 | 3,948.80 |
| | | | - List Item Discount on L Items | s 25.00/25.00% (S\$) _ | 1,064.75 | 874.20 |
| | | | | Total Parts (S\$) | 3,716.25 | 3,074.60 |
| | | | Report was unsubmitted during this | print-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|-----------------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | TO PANEL BEATING, WELDING, REMOVING DAMAGED PARTS AT REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETG. | | 900.00 | 700.00 |
| 2 | TO RESPRAY AFFECTED PART. | New | 800.00 | 600.00 |
| 3 | TO REMOVE & REFIT TAILGATE WINDSCREEN. | New | 120.00 | 120.00 |
| 4 | TO REMOVE & INSTALL REAR REVERSE SENSOR. | New | 60.00 | 50.00 |
| 5 | TO CHECK WIRINGS. | New | 30.00 | 30.00 |
| | Gross Labour Cost (S\$) | | 1,910.00 | 1,500.00 |
| | Report was unsubmitted during | this print-out. | | |

< END OF ESTIMATES >