5/20/25, 1:50 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110614/AUA3Q2

Date: 20/05/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230085664 **Claimant Vehicle** GBE8928X Insured Vehicle No: SLG9065A

No:

Date of Loss: 22/11/2024 Nature of Claim: TP Claim No: 3255653922SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE8928X**

Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2590718 Reg. Date: 20/04/2016 (Man. Year: 2016) Chassis No: KDH2010189919 Colour: White Odometer: 126713 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

195 R15C Front Tyre Size: 195 R15C Rear Tyre Size:

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,956.37	3,452.37	1,504.00	30.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,250.00	1,050.00	45.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,256.37	4,702.37	2,554.00	35.20
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	7,256.37	3,750.00	3,506.37	48.32
+ Loss of Use (7.0 x S	95.00/day) (S\$)	665.00		
+ Doc/s	Search Fee (S\$)	2.18		
No	ett Liability (S\$)	4,417.18		
Global Sum	Settlement (S\$)	4,400.00		

INSPECTION

Date of Assignment: 25/11/2024

Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Date Inspected: 25/11/2024 Inspected At:

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: **ADRIAN LING** Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,810.00 FL	*1,810.00 FL
2	1		*TAILGATE LOCK	Jammed	365.10 FL	*365.10 FL
3	1		*TAILGATE TOYOTA LOGO	Necessary	95.00 FL	*95.00 FL
4	1		*TAILGATE RUBBER	Not Necessary	456.80 FL	*- FL
5	1		*TAIL LAMP RH	Cracked	557.10 FL	*395.00 FL
6	1		*TAIL LAMP LH	Not Necessary	557.10 FL	*- FL
7	1		*TAIL LAMP LOWER GARNISH RH	Not Necessary	160.50 FL	*- FL
8	1		*TAIL LAMP LOWER GARNISH LH	Not Necessary	160.50 FL	*- FL
9	1		*REAR BUMPER	Deformed	680.00 FL	*680.00 FL
10	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	55.00 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	55.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	605.00 FL	*340.00 FL
13	1		*END PANEL	Dented	571.40 FL	*571.40 FL
14	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
15	1		*SPEED LIMIT STICKER 70KM/HR	Necessary	15.00 FS	*15.00 FS
16	1		*8 PAX STICKER	Necessary	15.00 FS	*15.00 FS
17	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	6,488.50 1,532.13	4,516.50
	- List Item Discount on L Items 25.00/25.00% (S\$)					1,064.13
				Total Parts (S\$)	4,956.37	3,452.37
			Report was unsubmitted	during this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	100.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT ANI WELD , TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	D New	1,200.00	700.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	400.00
4	LABOUR -REMOVE & REFIX TAILGATE WINDSCREEN	New	200.00	120.00
	Gross Labour Cost (S\$)		2,300.00	1,250.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >