



Yan.

Attn: Motor Claims Department  
Tel: 64193000

| No. | Item Descriptions                 | Qty | Unit Price      | Amount              | Remarks |
|-----|-----------------------------------|-----|-----------------|---------------------|---------|
| A.  | Spare Parts                       |     |                 |                     |         |
| 1   | Tailgate Dented                   | 1   |                 | \$1,810.00          | ✓       |
| 2   | Tailgate lock Jammed              | 1   |                 | \$365.10            | ✓       |
| 3   | Tailgate "Toyota" logo New        | 1   |                 | \$95.00             | ✓       |
|     | Tailgate Rubber New               | 1   |                 | \$456.80            | +       |
| 4   | Tail lamp RH Note could           | 1   |                 | <del>\$557.10</del> | + 395   |
| 5   | Tail lamp LH New                  | 1   |                 | \$557.10            | +       |
| 6   | Tail lamp lower garnish RH New    | 1   |                 | \$160.50            | +       |
| 7   | Tail lamp lower garnish LH New    | 1   |                 | \$160.50            | +       |
| 8   | Rear Bumper Dented                | 1   |                 | \$680.00            | ✓       |
| 9   | Rear Bumper side retainer RH Prop | 1   |                 | \$55.00             | +       |
| 10  | Rear Bumper side retainer LH New  | 1   |                 | \$55.00             | +       |
| 11  | Rear bumper reinforcement Dented  | 1   |                 | \$605.00            | ✓ 340   |
| 12  | End panel Dented                  | 1   |                 | \$571.40            | ✓       |
|     |                                   |     |                 |                     |         |
|     |                                   |     |                 |                     |         |
|     |                                   |     |                 |                     |         |
|     |                                   |     |                 |                     |         |
|     |                                   |     | Total           | \$6,128.50          |         |
|     |                                   |     | Less 25%        | \$1,532.13          |         |
|     |                                   |     | Sub Total 1     | \$4,596.37          |         |
| B.  | Spare Parts - S/NETT              |     |                 |                     |         |
| 1   | Rear Bumper clips New             | 10  | \$0.80          | \$80.00             | ✓ 30    |
| 2   | Speed limit sticker 70km/hr New   | 1   |                 | \$15.00             | ✓       |
| 3   | 8 pax sticker New                 | 1   |                 | \$15.00             | ✓       |
| 4   | Reverse sensor set Dented         | 1   |                 | <del>\$250.00</del> | 240     |
|     |                                   |     |                 |                     |         |
|     |                                   |     |                 |                     |         |
|     |                                   |     | Sub-Total 2     | \$360.00            |         |
|     |                                   |     | Total for Parts | \$4,956.37          |         |



AIG ASIA PACIFIC INSURANCE PTE LTD  
AIG BUILDING  
78 SHENTON WAY #07-16  
Singapore 079120

Total Pages : 2/2

Tel: 64193000

| No. | Item Descriptions                                                                                         | Qty | Unit Price        | Amount     | Remarks |
|-----|-----------------------------------------------------------------------------------------------------------|-----|-------------------|------------|---------|
| C.  | Labour                                                                                                    |     |                   |            |         |
| 1   | To check wiring.                                                                                          |     |                   | \$100.00   | 30      |
| 2   | Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. |     |                   | \$1,200.00 | 700     |
| 3   | Spray painting all affected parts & areas.                                                                |     |                   | \$800.00   | 4w      |
| 4   | Labour - Remove & refit tailgate windscreen                                                               |     |                   | \$200.00   | 120     |
|     |                                                                                                           |     |                   |            |         |
|     |                                                                                                           |     |                   |            |         |
|     |                                                                                                           |     | Total Labour      | \$2,300.00 |         |
|     |                                                                                                           |     | Total Repair Cost | \$7,256.37 |         |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

金



*f Premium Carz Services Pte Ltd*

total: 4702.37  
2/s: 3750

| Surveyor's Details |                           |
|--------------------|---------------------------|
| Name               | Adrian C                  |
| Contact            | 96893735                  |
| Survey Date        | 25/11/24                  |
| Recommender        | Authorize / Not Authorize |
| Before Paint       | Yes / No                  |

06 Dyz