



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: SERENE		Ref: CS/FCI24110615/Unp3m4(N) Date: 27/05/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 1299M	Veh. Inspected	FBM 3943S
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010413MFCT	Excess (\$)	0.00
Assign From	SWEE KEONG	Assign Date	28/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA XABRE TFX150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MH3RG3710HK026728	Colour	GREEN
Odometer	81811 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	110-70 R17	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140-70 R17	BRIDGESTONE	6 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	26/11/2024	Inspection Date	29/11/2024
Survey held at	BAN HOCK HIN CO.PTE LTD BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	