

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24110619/EQP3E2**Date:** 30/06/2025REFERENCEInsured/Claimant: KSB SINGAPORE (ASIA PACIFIC) PTE LTD
Date of Loss: 25/11/2024Policy No: 2070170945
Nature of Claim: OD Claim No: 5847893716SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8407H	Engine No:	DKY014783
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZF27MN012680
Reg. Date:	14/12/2020 (Man. Year: 2020)	Odometer:	49295 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,146.00	7,411.36	9,734.64	56.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,152.00	11,427.00	6,725.00	37.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,298.00	18,838.36	16,459.64	46.63
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	33,698.00	17,238.36	16,459.64	48.84
+ GST 9.00/9.00% (\$\$)	3,032.82	1,551.45	1,481.37	48.84
Nett Amount (\$\$)	36,730.82	18,789.81	17,941.01	48.84

INSPECTION

Date of Assignment: 29/11/2024

Date Inspected: 06/12/2024

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Repair	4,751.00 FS	*- FS
2	1		*REAR DOOR WEATHER OUTER SEAL - LH	Not Necessary	275.00 FS	*- FS
3	1		*REAR DOOR SEAL BRACKET - LH	Not Necessary	174.00 FS	*- FS
4	1		*REAR DOOR STONE CHIP PROTECTION FILM - LH	Not Necessary	248.00 FS	*- FS
5	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	390.00 FS	*- FS
6	1		*REAR DOOR SHELL OUTER SEAL - LH	Not Necessary	237.00 FS	*- FS
7	1		*REAR DOOR CATCH - LH	Not Necessary	150.00 FS	*- FS
8	1		*REAR DOOR EXTERIOR HANDLE - LH	Cut	436.00 FS	*348.80 FS
9	1		*REAR DOOR HANDLE CHROME CAP - LH	Not Necessary	116.00 FS	*- FS
10	1		*REAR DOOR HANDLE SENSOR - LH	Not Necessary	307.00 FS	*- FS
11	1		*REAR DOOR HANDLE CHROME TRIM PLATE - LH	Not Necessary	122.00 FS	*- FS
12	1		*REAR DOOR HANDLE SLIDE VALVE - LH	Not Necessary	16.00 FS	*- FS
13	2		*REAR DOOR HANDLE UNDERLAY - LH FRONT / REAR	Not Necessary	15.00 FS	*- FS
14	1		*REAR DOOR HANDLE MOUNTING BAR - LH	Not Necessary	203.00 FS	*- FS
15	1		*REAR SIDE PANEL - LH	Dented	6,138.00 FS	*4,910.40 FS
16	1		*REAR DOOR SILL TRIM STRIP - LH	Not Necessary	149.00 FS	*- FS
17	1		*SIDE MEMBER ATTACHMENT PARTS - LH	Necessary	153.00 FS	*122.40 FS
18	1		*SIDE MEMBER ADHESIVE TAPES - LH	Necessary	72.00 FS	*57.36 FS
19	1		*REAR QUARTER GLASS - LH	Necessary	1,020.00 FS	*816.00 FS
20	1		*WINDOW PRIMER	Necessary	27.00 FS	*21.52 FS
21	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
22	1		*METAL FILTER POWDER	Necessary	280.00 FS	*280.00 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
25	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
26	1		*SUNDRIES	Necessary	1,000.00 FS	*41.28 FS
27	2		*SOUND ABSORBER (SUPPLEMENTARY)	Necessary	267.00 FS	*213.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 17,146.00 7,411.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	0.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	1,800.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	1,800.00
5	TO REMOVE AND REINSTALL REAR BUMPER AND LHS SILL PANEL TRIM. TO DISMANTLE AND RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	3,250.00
6	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, REAR END PANELLING, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL AND LHS REAR DOOR HANDLE	New	5,400.00	3,025.00
7	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST	New	500.00	500.00
8	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	400.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			18,152.00	11,427.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >