Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: **ECICS Limited** From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 10 Eunos Road 8 #09-04A Singapore Post Centre Paya Ubi Industrial Park Singapore 408600 Singapore 408933

Attn: Sharon Tan Chow Yen Date: 02 Jul 2024

Preliminary Advice

Vehicle No : GQ2325C Accident Date : 24/06/2024

Make : NISSAN CABSTAR Policy No. : MCV24A00021601

: 27/06/2024 : S\$600.00 Assignment Date **Excess**

Est. Duration of Repair Date of Inspection : 02/07/2024 : 4

Inspection At : AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ)

3021A UBI ROAD 1, #01-42

SINGAPORE 408715

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,133.13
Revised Amount	:S\$	3,775.00
Check Items (Estimated)	:S\$	385.00
Total	:S\$	4,160.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	7,126.00
Salvage Value	:S\$	

Margin for Repair :S\$ 12,874.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: THE VEHICLE REPAIR ON LUMP SUM BASIS. (X)

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.