

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24110621/AMA3Q2  
**Date:** 11/04/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
**Claimant Vehicle No :** SNN6805R **Insured Vehicle No :** SLP5574B  
 Date of Loss: 27/11/2024 Nature of Claim: TP Claim No: MFL2024D0014214

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNN6805R**  
 Make & Model: TOYOTA ALPHARD, 2.5 7-SEATER SC CVT (A) Engine No: 2AR2415082  
 Reg. Date: 27/02/2021 (Man. Year: 2020) Chassis No: AGH300316940  
 Colour: White Odometer: 63772 km  
 Engine Capacity: 2493 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,657.67	8,424.92	4,232.75	33.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,090.00	2,870.00	57.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,617.67</b>	<b>10,514.92</b>	<b>7,102.75</b>	<b>40.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,400.00</b>		
<b>(S\$)</b>	17,617.67	8,400.00	9,217.67	52.32
<b>+ GST 9.00/9.00% (S\$)</b>	1,585.59	756.00	829.59	52.32
<b>Nett Amount (S\$)</b>	<b>19,203.26</b>	<b>9,156.00</b>	<b>10,047.26</b>	<b>52.32</b>
<b>+ Loss of Use (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>9,983.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,900.00</b>		

**INSPECTION**

Date of Assignment: 29/11/2024  
 Date Inspected: 29/11/2024 Inspected At: Chia Auto Services Pte Ltd (HQ)  
 23 Kaki Bukit Ave 4, #04-01 Vicom Inspection Center  
 Singapore 415933  
 Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2025)
<b>Parts:</b>	M1-MPV	TOYOTAALPHARD 2.5 7-SEATER SC CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNN6805R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,155.30 FL	*2,155.30 FL
2	1		*TAILGATE LOGO	Not Necessary	95.00 FL	*- FL
3	1		*TAILGATE APHARD EMBLEM	Necessary	90.00 FL	*90.00 FL
4	2		*TAILGATE DAMPER	Not Necessary	180.00 FL	*- FL
5	2		*TAILGATE HINGE	Not Necessary	560.00 FL	*- FL
6	1		*TAILGATE LAMP LH	Cracked	890.00 FL	*789.00 FL
7	1		*TAILGATE INNER TRIM BOARD	Cracked	1,155.20 FL	*895.00 FL
8	1		*TAILGATE SIDE SENSOR LH	Bent	1,255.30 FL	*940.00 FL
9	1		*TAILGATE LOCK	Not Necessary	520.00 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Not Necessary	350.00 FL	*- FL
11	1		*TAILGATE ANTENNA SWITCH	Not Necessary	180.00 FL	*- FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	250.00 FL	*250.00 FL
13	1		*REAR BUMPER	Distorted	880.00 FL	*880.00 FL
14	1		*REAR BUMPER TOWING COVER LH	Distorted	80.00 FL	*45.00 FL
15	1		*REAR BUMPER SIDE RETAINER LH	Cracked	110.00 FL	*110.00 FL
16	1		*REAR BUMPER REFLECTOR LH	Cracked	150.00 FL	*150.00 FL
17	1		*REAR PARKING SENSOR	Damaged	320.00 FL	*320.00 FL
18	1		*REAR QUARTER BUMPER LH	Deformed	350.00 FL	*350.00 FL
19	1		*REAR QUARTER BUMPER SIDE RETAINER LH	Not Necessary	130.00 FL	*- FL
20	1		*TAILLAMP LH	Cracked	1,055.30 FL	*940.00 FL
21	1		*REAR FENDER INNER TRIM LH	Cracked	1,355.60 FL	*1,355.60 FL
22	1		*REAR END PANEL	Dented	860.00 FL	*860.00 FL
23	1		*REAR END PANEL TOP GARNISH	Deformed	250.00 FL	*250.00 FL
24	1		*REAR FLOOR PANEL	Repair	980.00 FL	*- FL
25	1		*REAR FLOOR PANEL MAT	Not Necessary	1,155.20 FL	*- FL
26	1		*REAR COMPARTMENT COVER LH	Deformed	560.00 FL	*280.00 FL
27	1		*REAR BUMPER UNDER COVER LH	Deformed	280.00 FL	*280.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET TAILGATE TRIM BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
30	1		*SET TAILGATE SIDE SENSOR CLIPS	Necessary	20.00 FS	*20.00 FS
31	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
36	1		*REAR FLOOR PANEL SEALANT	Not Necessary	120.00 FS	*- FS
37	1		*SET REAR FLOOR PANEL MAT CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>16,706.90</b>	<b>11,159.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	4,049.23	2,734.98
<b>Total Parts (S\$)</b>	<b>12,657.67</b>	<b>8,424.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	800.00
3	TUFF COAT	New	200.00	80.00
4	WIRING CHECK	New	80.00	30.00
5	TO REMOVE AND REFIX INNER CAR CUSHION	New	180.00	80.00
6	TO REMOVE AND REFIX TAILGATE MECHANISM	New	180.00	80.00
7	TO REMOVE AND REFIX REVERSE SENSOR AND SETTING	New	100.00	50.00
8	TO REMOVE AND REFIX REVERSE CAMERA AND SETTING	New	100.00	50.00
9	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,960.00</b>	<b>2,090.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**