

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To in \_\_\_\_\_ Vehicle NO: \_\_\_\_\_

at \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client Record)

Make of Val: \_\_\_\_\_

\*\*\*

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Bel. or Metal Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time Action / Instruction

TP III

MV:

PV:

Nett:

Veh No: SNN680SR Yr Regn: 2021 / Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard C.D. 2493

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 63772 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: AGH300316940

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 29/11/24

Survey held at Chia

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2)

Report Format:

1) \_\_\_\_\_

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

: Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Inve (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

3 + R8. 81

Photos

Others

COE Expiry: ↓

Estimate given during: Yes ( )

1st Survey: No ( )

## CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

|                               |                         |
|-------------------------------|-------------------------|
| <b>ATTENTION:</b>             | MOTOR CLAIMS DEPARTMENT |
| <b>DATE:</b>                  | 29-11-24                |
| <b>CLAIM TYPE:</b>            | T/P CLAIM               |
| <b>TO:</b>                    | INDIA                   |
| <b>VEHICLE DETAILS</b>        |                         |
| <b>VEHICLE NO:</b>            | SNN6805R                |
| <b>MAKE &amp; MODEL:</b>      | TOYOTA ALPHARD          |
| <b>CHASSIS NO:</b>            |                         |
| <b>ACCIDENT DETAILS</b>       |                         |
| <b>DATE:</b>                  | 27 November, 2024       |
| <b>TIME:</b>                  | 2200HRS                 |
| <b>THIRD PARTY REQUESTOR:</b> | JACK LI                 |

### CLAIM DETAILS: PARTS

| S/N: | DESCRIPTION                                     | QTY: | UNIT LIST PRICE | TOTAL LIST PRICE |     |
|------|---|------|-----------------|------------------|-----|
| 1    | TAILGATE <i>Dented</i>                          | 1    | \$ 2,155.30     | \$ 2,155.30      | ✓   |
| 2    | TAILGATE LOGO <i>New</i>                        | 1    | \$ 95.00        | \$ 95.00         | +   |
| 3    | TAILGATE ALPHARD EMBLEM <i>new</i>              | 1    | \$ 90.00        | \$ 90.00         | ✓   |
| 4    | TAILGATE DAMPER <i>new</i>                      | 2    | \$ 90.00        | \$ 180.00        | +   |
| 5    | TAILGATE HINGE <i>new</i>                       | 2    | \$ 280.00       | \$ 560.00        | +   |
| 6    | TAILGATE LAMP LH <i>crushed</i>                 | 1    | \$ 890.00       | \$ 890.00        | ✓   |
| 7    | TAILGHATE INNER TRIM BOARD <i>crushed</i>       | 1    | \$ 1,155.20     | \$ 1,155.20      | 855 |
| 8    | TAILGATE SIDE SENSOR LH <i>But</i>              | 1    | \$ 1,255.30     | \$ 1,255.30      | ✓   |
| 9    | TAILGATE LOCK <i>new</i>                        | 1    | \$ 520.00       | \$ 520.00        | +   |
| 10   | TAILGATE WEATHERSTRIP <i>new</i>                | 1    | \$ 350.00       | \$ 350.00        | x   |
| 11   | TAILGATE ANTENNA SWITCH <i>new</i>              | 1    | \$ 180.00       | \$ 180.00        | x   |
| 12   | TAILGATE WINDSCREEN MOULDING <i>new</i>         | 1    | \$ 250.00       | \$ 250.00        | ✓   |
| 13   | REAR BUMPER <i>Dented</i>                       | 1    | \$ 880.00       | \$ 880.00        | ✓   |
| 14   | REAR BUMPER TOWING COVER LH <i>Dented</i>       | 1    | \$ 80.00        | \$ 80.00         | 25  |
| 15   | REAR BUMPER SIDE RETAINER LH <i>crushed</i>     | 1    | \$ 110.00       | \$ 110.00        | ✓   |
| 16   | REAR BUMPER REFLECTOR LH <i>crushed</i>         | 1    | \$ 150.00       | \$ 150.00        | ✓   |
| 17   | REAR PARKING SENSOR <i>Dented</i>               | 1    | \$ 320.00       | \$ 320.00        | ✓   |
| 18   | REAR QUARTER BUMPER LH <i>Dented</i>            | 1    | \$ 350.00       | \$ 350.00        | ✓   |
| 19   | REAR QUARTER BUMPER SIDE RETAINER LH <i>new</i> | 1    | \$ 130.00       | \$ 130.00        | +   |
| 20   | TAILLAMP LH <i>crushed</i>                      | 1    | \$ 1,055.30     | \$ 1,055.30      | ✓   |
| 21   | REAR FENER INNER TRIM LH <i>crushed</i>         | 1    | \$ 1,355.60     | \$ 1,355.60      | ✓   |

|    |  |   |             |             |      |
|----|--|---|-------------|-------------|------|
| 22 | REAR END PANEL <i>Dented</i>             | 1 | \$ 860.00   | \$ 860.00   | ✓    |
| 23 | REAR END PANEL TOP GARNISH <i>dented</i> | 1 | \$ 250.00   | \$ 250.00   | ✓    |
| 24 | REAR FLOOR PANEL <i>Repair</i>           | 1 | \$ 980.00   | \$ 980.00   | +    |
| 25 | REAR FLOOR PANEL MAT <i>new</i>          | 1 | \$ 1,155.20 | \$ 1,155.20 | +    |
| 26 | REAR COMPARTMENT COVER LH <i>dented</i>  | 1 | \$ 560.00   | \$ 560.00   | 280. |

*Rear Bumper under cover LH*  
*dented*

*#280*  
TOTAL PRICE  
LESS 25%

\$ 15,916.90  
\$ 3,979.23

SUB TOTAL PRICE \$ 11,937.68

**SPECIAL NETT ITEMS**

| S/N:         | DESCRIPTION                                      | QTY: | UNIT LIST PRICE | TOTAL LIST PRICE |     |
|--------------|--|------|-----------------|------------------|-----|
| 1            | REAR NUMBER PLATE <i>new</i>                     | 1    | \$ 50.00        | \$ 50.00         | +   |
| 2            | TAILGATE INNER TRIM BOARD CLIPS(SET) <i>new</i>  | 1    | \$ 20.00        | \$ 20.00         | ✓   |
| 3            | TAILGATE SIDE SENSOR CLIPS(SET) <i>new</i>       | 1    | \$ 20.00        | \$ 20.00         | -   |
| 4            | TAILGATE WINDSCREEN SELANT <i>new</i>            | 1    | \$ 100.00       | \$ 100.00        | 60  |
| 5            | REAR BUMPER CLIPS(SET) <i>new</i>                | 1    | \$ 20.00        | \$ 20.00         | ✓   |
| 6            | REAR FENDER INNER TRIM CLIPS(SET) <i>new</i>     | 1    | \$ 20.00        | \$ 20.00         | ✓   |
| 7            | REAR END PANEL SEALANT <i>new</i>                | 1    | \$ 120.00       | \$ 120.00        | 60. |
| 8            | REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i> | 1    | \$ 20.00        | \$ 20.00         | ✓   |
| 9            | REAR FLOOR PANEL SEALANT <i>new</i>              | 1    | \$ 120.00       | \$ 120.00        | +   |
| 10           | REAR FLOOR PANEL MAT CLIPS(SET) <i>new</i>       | 1    | \$ 20.00        | \$ 20.00         | +   |
| <b>TOTAL</b> |  |      |                 | <b>\$ 510.00</b> |     |

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

|              |  |   |             |                    |      |
|--------------|--|---|-------------|--------------------|------|
| 1            | PANEL BEATING, REMOVAL AND REPLACING PARTS     | 1 | \$ 2,000.00 | \$ 2,000.00        | 800. |
| 2            | TO SPRAY PAINT AFFECTED AREA                   | 1 | \$ 2,000.00 | \$ 2,000.00        | 800  |
| 3            | TUFF COAT                                      | 1 | \$ 200.00   | \$ 200.00          | 60   |
| 4            | WIRING CHECK                                   | 1 | \$ 80.00    | \$ 80.00           | 30   |
| 5            | TO REMOVE AND REFIX INNER CAR CUSHION          | 1 | \$ 180.00   | \$ 180.00          | 60   |
| 6            | TO REMOVE AND REFIX TAILGATE MECHANISM         | 1 | \$ 180.00   | \$ 180.00          | 60   |
| 7            | TO REMOVE AND REFIX REVERSE SENSOR AND SETTING | 1 | \$ 100.00   | \$ 100.00          | 50   |
| 8            | TO REMOVE AND REFIX REVERSE CAMERA AND SETTING | 1 | \$ 100.00   | \$ 100.00          | 50   |
| 9            | TO REMOVE AND REFIX REAR WINDSCREEN            | 1 | \$ 120.00   | \$ 120.00          | ✓    |
| <b>TOTAL</b> |  |   |             | <b>\$ 4,960.00</b> |      |

**ESTIMATE REPORT**

TOTAL PARTS COST \$ 12,447.68

TOTAL LABOUR COST \$ 4,960.00  
TOTAL REPAIR COST \$ 17,407.68

**APPROVED DETAILS:**

---

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian King,  
w/s 29/11/24.  
06 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: