

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110622/UMA3Q2**Date:** 17/03/2025**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MFL0003653
Claimant Vehicle No :	SMJ3427B	Insured Vehicle No :	GBD1403U
Date of Loss:	26/11/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0014183

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3427B	Engine No:	LEB1435309
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP51329353
Reg. Date:	28/02/2019 (Man. Year: 2018)	Odometer:	175931 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,476.07	7,408.63	5,067.44	40.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,970.00	1,170.00	37.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,616.07	9,378.63	6,237.44	39.94
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	15,616.07	7,500.00	8,116.07	51.97
+ GST 9.00/9.00% (S\$)	1,405.45	675.00	730.45	51.97
Nett Amount (S\$)	17,021.52	8,175.00	8,846.52	51.97
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		8,475.00		
Liab Amount (50.00%) (S\$)		4,237.50		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		4,295.75		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment:	29/11/2024	
Date Inspected:	29/11/2024	Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2025)
Parts: 144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMJ3427B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	723.60 FL	*581.20 FL
2	1		*FRONT BUMPER SIDE GRILLE -RH	Grazed	62.50 FL	*62.50 FL
3	1		*FRONT BUMPER SIDE RETAINER LH/RH	N/S Not Necessary /O/S Cracked	91.00 FL	*45.50 FL
4	1		*FRONT DOOR RH	Dented / Bent	1,053.60 FL	*1,053.60 FL
5	1		*FRONT DOOR SIDE MIRROR	Damaged	615.20 FL	*480.50 FL
6	1		*FRONT DIIR OUTER HANDLE	Cut	182.60 FL	*182.60 FL
7	1		*SET FRONT DOOR OUTER KEY	Damaged	211.50 FL	*211.50 FL
8	1		*FRONT DOOR GLASS OUTER MOULDING	Serviceable	151.20 FL	*- FL
9	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	210.60 FL	*- FL
10	1		*FRONT DOOR GLASS REGULATOR	Bent	491.50 FL	*291.20 FL
11	1		*FRONT DOOR GLASS GUIDE	Not Necessary	86.90 FL	*- FL
12	1		*FRONT DOOR INNER LOCK	Damaged	286.60 FL	*286.60 FL
13	1		*FRONT DOOR INNER TRIM BOARD	Deformed / Torn	761.99 FL	*761.99 FL
14	1		*FRONT DOOR INSULATOR	Not Necessary	130.20 FL	*- FL
15	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	141.20 FL	*- FL
16	1		*FRONT DOOR CHECKER	Twisted	89.50 FL	*89.50 FL
17	2		*FRONT DOOR HINGE	Bent	191.00 FL	*191.00 FL
18	1		*FRONT FENDER RH	Repair	425.10 FL	*- FL
19	1		*FRONT FENDER INNER SHIELD	Twisted	161.20 FL	*161.20 FL
20	1		*FRONT FENDER INNER PANEL MEMBER	Dented / Bent	410.60 FL	*410.60 FL
21	1		*FRONT FENDER EMBLEM	Necessary	68.60 FL	*68.60 FL
22	1		*FRONT FENDER SIGNAL LAMP	Not Necessary	58.80 FL	*- FL
23	1		*FRONT SHOCK ABSORBER RH	Bent	410.60 FL	*410.60 FL
24	1		*FRONT LOWER ARM	Bent	376.60 FL	*376.60 FL
25	1		*FRONT KNUCKLE ARM	Bent	405.90 FL	*405.90 FL
26	1		*FRONT WHEEL HUB	Bent	210.60 FL	*210.60 FL
27	1		*FRONT WHEEL BEARING	Necessary	186.90 FL	*186.90 FL
28	1		*FRONT ANIT ROLL BAR	Not Necessary	310.50 FL	*- FL
29	1		*FRONT ANIT ROLL BAR LINK	Not Necessary	86.60 FL	*- FL
30	1		*FRONT DRIVE SHAFT RH	Not Necessary	1,210.50 FL	*- FL
31	1		*FRONT HEADLAMP RH	Cracked	1,671.50 FL	*1,480.20 FL
32	1		*SIDE STILL PANEL RH	Repair	691.90 FL	*- FL
33	1		*SIDE STILL PANEL GARNISH	Deformed / Torn	586.90 FL	*586.90 FL
34	1		*REAR DOOR RH	Repair	991.60 FL	*- FL
35	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
36	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*30.00 FS
37	1		*FRONT SPORT WHEEL RH	Warped	650.00 FS	*400.00 FS
38	1		*FRONT TYRE RH	Serviceable	250.00 FS	*- FS
39	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
40	1		*SET FRONT AND REAR DOOR VISOR	Necessary	350.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,225.09	9,115.79
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,749.02	1,707.16
Total Parts (\$\$)	12,476.07	7,408.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING	New	50.00	20.00
2	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	New	250.00	120.00
3	TO PERFORM COMPUTERISE 4 WHEEL ALIGHTMENT	New	120.00	80.00
4	TO TUFF KOTE	New	120.00	50.00
5	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	1,400.00	600.00
6	TO PANEL BEAT ,CUT ,WELD REMOVE & REPLACE DAMAGE PARTS	New	1,200.00	1,100.00
			Gross Labour Cost (\$)	3,140.00
				1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >