

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 3774D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	NOT NECESSARY	1,989.90	-
2	TAILGATE LOWER HINGE @\$55.50	O/S BENT	111.00	55.50
1	TAILGATE LATCH RH	BENT	312.00	180.00
1	REAR END PANEL	NOT NECESSARY	455.00	-
1	REAR SIDE GATE RH	DENTED	1,857.90	1,857.90
1	REAR CORNER PANEL RH	BENT	201.00	201.00
1	REAR CORNER PANEL STOPPER RH	BROKEN	38.00	38.00
1	REAR NUMBER PLATE BRACKET	NOT NECESSARY	106.60	-
	LESS 25% DISCOUNT		-1,267.85	-583.10
			3,803.55	1,749.30
	SPECIAL NETT ITEMS			
1	SIDE GATE ADVERTISMENT STICKER RH (SN)	NECESSARY	400.00	400.00
2	TAILGATE STICKER 70KM/H, 13PAX (SN)	NOT NECESSARY	40.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	TAILGATE DYNA STICKER (SN)	NOT NECESSARY	20.00	-
			510.00	400.00
	<u>LABOUR</u>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.		950.00	500.00
	SPRAY PAINTING.		850.00	500.00
	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS.		50.00	30.00
	REMOVE AND REFIX UPHOLSTERY TO FACILITATE THE REPAIR WORKS.	NOT NECESSARY	150.00	-
			2,000.00	1,030.00
	GRAND TOTAL		6,313.55	3,179.30

Report Ref No. CS/LIP24110624/Eqh3e2(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,550.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP24110624/Eqh3e2(N)

MARKET VALUE: \$66,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9.588.00=NETT VALUE: \$56,412.00



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser