



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9528S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S/F FENDER	BENT	982.90	755.20
1	O/S/F FENDER INNER SHIELD	SERVICEABLE	226.60	-
1	EMBLEM VVTI	NECESSARY	38.50	38.50
1	O/S HEADLAMP	BROKEN	3,246.10	1,137.40
1	FRONT BUMPER	BUCKLED	458.10	458.10
1	O/S FRONT BUMPER RETAINER	DISTORTED	92.40	92.40
1	FRONT BUMPER O/S FOG LAMP	SERVICEABLE	395.40	-
1	O/S WING MIRROR	SERVICEABLE	385.00	-
	LESS 25% DISCOUNT		-1,456.25	-620.40
			4,368.75	1,861.20
	<u>SPECIAL NETT ITEMS</u>			
1	O/S/F SPORT RIMS (SN)	SERVICEABLE	2,173.50	-
			2,173.50	-
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
	WIRE CHECKING .		50.00	20.00
	COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			1,800.00	820.00
	GRAND TOTAL		8,342.25	2,681.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00

Report Ref No. CD/CTI24120001/Kua3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.