

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120004/KUA3Q2  
Date: 28/03/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0007304
Claimant Vehicle No :	GX5858A	Insured Vehicle No :	GBK9476U
Date of Loss:	15/11/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0013776

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX5858A	Engine No:	HIDDEN
Make & Model:	BYD ET3, (A)	Chassis No:	LC0CE4DB9P0174733
Reg. Date:	09/09/2024 (Man. Year: 2023)	Odometer:	5922 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Linglong 9 mm	Rear Left Side:	Linglong 9 mm
Front Right Side:	Linglong 9 mm	Rear Right Side:	Linglong 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,782.93	6,913.00	2,869.93	29.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,500.00	210.00	12.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,492.93	8,413.00	3,079.93	26.80
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	11,492.93	6,700.00	4,792.93	41.70
+ GST 9.00/9.00% (S\$)	1,034.36	603.00	431.36	41.70
Nett Amount (S\$)	12,527.29	7,303.00	5,224.29	41.70
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,865.18		

INSPECTION

Date of Assignment:	02/12/2024		
Date Inspected:	02/12/2024	Inspected At:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #07-02 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 04 Mar 2025)	
<b>Parts:</b>	N/A	BYD ET3 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GX5858A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR BUMPER</b> (WCP)	Buckled	1,170.00 F	*1,050.00 F
2	2		<b>*REAR BUMPER OUTER SIDE RETAINER</b> (WCP)	Serviceable	91.00 F	*- F
3	2		<b>*REAR BUMPER INNER SIDE RETAINER</b> (WCP)	Serviceable	102.00 F	*- F
4	1		<b>*REAR BUMPER 3RD BRAKE LAMP</b> (WCP)	Cracked	380.00 F	*380.00 F
5	2		<b>*REAR BUMPER REVERSE SENSOR</b> (WCP)	Dented / Scratched	390.00 F	*390.00 F
6	1		<b>*TAIL GATE</b> (WCP)	Bent	4,200.00 F	*3,400.00 F
7	1		<b>*TAILGATE LOCK</b> (WCP)	Repair	199.00 F	*- F
8	1		<b>*TAIL GATE WEATHERSTRIP</b> (WCP)	Serviceable	244.00 F	*- F
9	1		<b>*TAIL GATE OUTER CHROME GARNISH</b> (WCP)	Warped	420.00 F	*420.00 F
10	1		<b>*TAIL GATE BYD LOGO EMBLEM</b> (WCP)	Serviceable	110.50 F	*- F
11	1		<b>*TAIL GATE T3 EMBLEM</b> (WCP)	Necessary	40.00 F	*40.00 F
12	1		<b>*TAIL GATE INNER TRIM BOARD</b> (WCP)	Serviceable	425.80 F	*- F
13	1		<b>*REAR END PANEL</b> (WCP)	Bent	550.00 F	*550.00 F
14	2		<b>*CAR PLATE LAMP</b> (WCP)	Serviceable	144.00 F	*- F
15	1		<b>*SET REAR INNER TRIM BOARD CLIP</b>	Necessary	30.00 FS	*30.00 FS
16	1		<b>*REAR CAMERA</b>	Serviceable	400.00 FS	*- FS
17	1		<b>*REAR END PANEL SEALANT</b>	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>8,936.30</b>	<b>6,290.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	846.63	623.00
<b>Total Parts (\$\$)</b>	<b>9,782.93</b>	<b>6,913.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT DAMAGED PARTS	New	600.00	600.00
2	TRANSFER OD EXISTING TAILGATE MECHANISM TO NEW TAILGATE	New	90.00	60.00
3	REMOVE & REFIX TAILGATE WINDSCREEN GLASS	New	120.00	120.00
4	REMOVE & REFIX REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	90.00	60.00
5	REMOVE & REFIX /REPLACE REAR REVERSE CAMERA & CONDUCT DISTANCE SAFETY SETTING	New	70.00	40.00
6	WIRING /BULB CHECKING /FOCUSING	New	40.00	20.00
7	TO PUTTY & SPRAY PAINT ACCIDENT DAMAGED PARTS AND ADJACENT PANELS	New	700.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,710.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >