

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24120005/AMA3Q2**Date:** 11/04/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MPC0000937
Claimant Vehicle No : SLR9143A **Insured Vehicle No :** SGK6561S
 Date of Loss: 27/11/2024 Nature of Claim: TP Claim No: MPC2024D0014239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR9143A**
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6317409
 Reg. Date: 30/08/2017 (Man. Year: 2017) Chassis No: GP71114281
 Colour: Red Odometer: 133852 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,815.28	4,852.00	6,963.28	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,890.00	2,290.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,995.28	6,742.00	9,253.28	57.85
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	15,995.28	5,400.00	10,595.28	66.24
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,907.25		
Global Sum Settlement (S\$)		5,900.00		

INSPECTION

Date of Assignment: 02/12/2024
 Date Inspected: 02/12/2024 Inspected At: FONG MOTORS RENTAL PTE LTD (HQ)
 1 Kaki Bukit Ave 6 #01-45 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Mar 2025)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9143A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	986.90 FL	*986.90 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	90.40 FL	*- FL
3	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	90.80 FL	*- FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	19.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Not Necessary	64.00 FL	*- FL
6	2		*REAR BUMPER SIDE SPONGE	Not Necessary	94.00 FL	*- FL
7	1		*TAILGATE	Dented	1,193.20 FL	*1,193.20 FL
8	1		*TAILGATE OUTER MOULDING	Not Necessary	383.80 FL	*- FL
9	1		*TAILGATE LOGO	Not Necessary	38.40 FL	*- FL
10	1		*TAILGATE SHUTTLE EMBLEM	Necessary	55.40 FL	*55.40 FL
11	1		*TAILGATE HYBRID EMBLEM	Necessary	60.20 FL	*60.20 FL
12	1		*TAILGATE LAMP	N/S Cracked	761.80 FL	*380.90 FL
13	2		*TAILGATE DAMPER	Not Necessary	250.00 FL	*- FL
14	2		*TAILGATE HINGE	Not Necessary	78.80 FL	*- FL
15	1		*TAILGATE INNER HOLDER	Not Necessary	40.00 FL	*- FL
16	1		*TAILGATE INNER LOCK	Damaged	298.40 FL	*298.40 FL
17	1		*TAILGATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Cut	166.50 FL	*166.50 FL
19	1		*TAILGATE LOCK ANTENNA	Not Necessary	180.20 FL	*- FL
20	1		*TAILGATE INNER TRIM BOARD	Cracked	320.40 FL	*320.40 FL
21	1		*TAILGATE WINDSCREEN MOULDING	Necessary	149.20 FL	*149.20 FL
22	1		*TAILGATE BUZZER	Not Necessary	170.00 FL	*- FL
23	2		*TAILLAMP	Not Necessary	1,041.00 FL	*- FL
24	2		*TAILLAMP LOWER PANEL OUTER	Not Necessary	510.00 FL	*- FL
25	2		*TAILLAMP LOWER PANEL INNER	Not Necessary	398.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM	Not Necessary	799.20 FL	*- FL
27	1		*REAR END PANEL	Dented	681.20 FL	*681.20 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	155.00 FL	*155.00 FL
29	1		*REAR EXHAUST PIPE	Not Necessary	688.20 FL	*- FL
30	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	39.20 FL	*- FL
31	1		*REAR EXHAUST PIPE GASKET	Not Necessary	31.60 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	178.60 FL	*- FL
33	1		*REAR FLOOR PANEL	Repair	1,180.00 FL	*- FL
34	1		*REAR FLOOR PANEL TOP OUTER BOARD	Deformed	585.20 FL	*585.20 FL
35	2		*REAR FLOOR PANEL TOP SIDE BOARD	Not Necessary	191.40 FL	*- FL
36	1		*REAR FLOOR PANEL TOP INNER BOARD	Not Necessary	567.30 FL	*- FL
37	1		*REAR PLASTIC STROAGE BOX	Deformed	495.00 FL	*495.00 FL
38	1		*REAR TOOLS SPONGE TRAY	Not Necessary	165.40 FL	*- FL
39	1		*REAR JACK COVER	Not Necessary	122.40 FL	*- FL
40	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
41	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
43	1		*SET TAILGATE OUTER MOULDING CLIPS	Not Necessary	30.00 FS	*- FS
44	1		*TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
45	2		*SET TAILLAMP CLIPS	Not Necessary	40.00 FS	*- FS
46	2		*SET REAR FENDER INNER TRIM BOARD	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
48	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
49	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
50	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,484.10	5,957.50
- List Item Discount on L Items 20.00/20.00% (\$)	2,668.82	1,105.50
Total Parts (\$)	11,815.28	4,852.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,500.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,500.00	700.00
3	WIRING CHECK	New	100.00	30.00
4	TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE TAILGATE GLASS	New	180.00	120.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE REAR VIDEO RECORDER	New	100.00	0.00
10	TO REMOVE REVERSE SENSOR	New	100.00	50.00
11	TO REMOVE REAR CAMERA	New	100.00	50.00
Gross Labour Cost (\$\$)			4,180.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >