

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24120007/RPA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_04
Claimant Vehicle No : SGU4052E **Insured Vehicle No :** SHD2306P
Date of Loss: 28/11/2024 Nature of Claim: TP Claim No: MFL2024D0014266

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU4052E**
Make & Model: TOYOTA WISH, 1.8 X LIMITED (A) Engine No: 1ZZ2792181
Reg. Date: 14/05/2007 (Man. Year: 2007) Chassis No: ZNE100345056
Colour: Grey Odometer: 304233 km
Engine Capacity: 1794 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,439.69	4,111.79	2,327.90	36.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,860.00	1,540.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,839.69	5,971.79	3,867.90	39.31
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	9,839.69	4,750.00	5,089.69	51.73
+ GST 9.00/9.00% (S\$)	885.57	427.50	458.07	51.73
Nett Amount (S\$)	10,725.26	5,177.50	5,547.76	51.73
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		5,879.68		

INSPECTION

Date of Assignment: 03/12/2024
Date Inspected: 03/12/2024 Inspected At: Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3, #01-80
Singapore 159723
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)
Parts:	M1-MPV	TOYOTA WISH 1.8 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU4052E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,699.60 FL	*1,699.60 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	230.55 FL	*230.55 FL
3	1		*REAR TAILGATE LOGO	Necessary	60.00 FL	*60.00 FL
4	1		*REAR TAILGATE CHROME WISH	Cracked	320.00 FL	*320.00 FL
5	1		*REAR TAILGATE LOCK	Serviceable	249.40 FL	*- FL
6	1		*REAR WEATHERSTRIP	Serviceable	320.80 FL	*- FL
7	1		*REAR TAILGATE INNER TRIM BOARD	Scratched	480.75 FL	*480.75 FL
8	1		*REAR RH LAMP	Scratched	680.00 FL	*680.00 FL
9	1		*REAR LH LAMP	Serviceable	680.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	1,250.80 FL	*1,250.80 FL
11	2		*REAR BUMPER SIDE RETAINER *SHORT	Serviceable	80.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER *LONG	Serviceable	130.00 FL	*- FL
13	1		*REAR BUMPER REFLECTOR	Serviceable	135.00 FL	*- FL
14	1		*REAR BUMPER CENTRE BRACKET	Serviceable	195.00 FL	*- FL
15	2		*REAR REINFORCEMENT ARM	Serviceable	210.00 FL	*- FL
16	1		*REAR END PANEL (INNER)	Serviceable	620.00 FL	*- FL
17	1		*REAR END PANEL (OUTER)	Bent	580.69 FL	*580.69 FL
18	1		*REAR END PANEL TOP GARNISH	Serviceable	285.00 FL	*- FL
19	1		*CAR PLATE NUMBER	Missing	40.00 FS	*35.00 FS
20	1		*REAR TAILGATE CLASS SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	35.00 FS	*30.00 FS
22	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	24.00 FS	*- FS
24	2		*REAR FENDER SHIELD CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,491.59	5,437.39
- List Item Discount on L Items 25.00/25.00% (\$)	2,051.90	1,325.60
Total Parts (\$)	6,439.69	4,111.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS.	New	1,000.00	600.00
2	LABOUR REMOVE/ REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA (INCLUDED FENDER).	New	1,000.00	600.00
3	CHECK WIRING SYSTEM & LIGHT.	New	100.00	30.00
4	ANTI RUST TREATMENT.	New	120.00	40.00
5	TO REMOVE/ REFIX/ REPLACE REAR REVERSE CAMERA.	New	150.00	100.00
6	TO REMOVE/ REFIZ REAR INNER COMPARTMENT/ TRIM BOARD FOR FACILITATE REPAIR.	New	200.00	60.00
7	TO REMOVE/ REFIX/ REPLACE REAR TAILGATE INNER TRIM BOARD, TOP SPOILER, WIPER MECHENISM TO NEW TAILGATE.	New	200.00	60.00
8	TO REMOVE/ REPLACE REAR TAILGATE GLASS.	New	150.00	120.00
9	TO REMOVE/ REFIX TAILGATE TOP SPOILER TO NEW TAILGATE.	New	100.00	0.00
10	COMPUTER DIAGNOSTIC (RESET NECESSARY ELECTRONIC FUNCTION).	New	380.00	250.00
Gross Labour Cost (\$\$)			3,400.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >