



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNS 7222P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	1,461.00	1,461.00
1	FRONT BUMPER SIDE HOLDER	CRACKED	98.00	98.00
1	FRONT BUMPER SENSOR	NOT NECESSARY	265.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	1,012.00	-
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	221.00	-
1	HEADLAMP	CUT	3,782.00	3,782.00
1	FRONT STAY ARM	NOT NECESSARY	295.00	-
1	FRONT LOWER ARM	NOT NECESSARY	471.50	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	487.80	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	385.20	-
1	FRONT CONTROL ARM	NOT NECESSARY	286.00	-
1	FRONT WHEEL HUB C/W BEARING	NOT NECESSARY	314.40	-
	LESS 10% DISCOUNT		-907.89	-534.10
			8,171.01	4,806.90
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	1,250.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	280.00	-
			1,590.00	30.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		800.00	300.00
	SPRAY PAINTING.		800.00	400.00
	WIRING.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	30.00
	TO DISMANTLE FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	250.00	-

Report Ref No. CS/INC24120011/Anh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,550.00	760.00
GRAND TOTAL			12,311.01	5,596.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,400.00

Report Ref No. CS/INC24120011/Anh3e2(N)

TOTAL FOR SPARE PARTS: \$ 9,761.01 \$ 4,836.90

TOTAL FOR LABOUR : \$ 2,550.00 \$ 760.00

TOTAL REPAIR COST: \$ 12,311.01 \$ 5,596.90

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.