



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC24120012/Uvh3m4(N)

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 02/01/2025

ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 6322G	Veh. Inspected	GBJ 4649B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305762-002	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	02/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFHT02PX00248932	Colour	SILVER
Odometer	39448 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/11/2024	Inspect Date / Time	03/12/2024 (02:00 PM)
Survey held at	HUAT AUTOMOBILE AIR-CON SERVICE 3007 UBI ROAD 1, #01-404, KAMPONG UBI INDUSTRIAL ESTATE, SINGAPORE 408701		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days