

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24120013/AMA3Q2
Date: 28/03/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700083674
Claimant Vehicle No :	SKR93G	Insured Vehicle No :	SFP1168M
Date of Loss:	21/11/2024	Nature of Claim:	TP
		Claim No:	5133268048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR93G		
Make & Model:	MERCEDES-BENZ S500L, 3.0 AMG LINE PREMIUM+ M-HYBRID (A)	Engine No:	25693030263159
Reg. Date:	30/08/2022 (Man. Year: 2020)	Chassis No:	W1K2231632A015129
Colour:	Black	Odometer:	38234 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/25 R22	Rear Tyre Size:	295/25 R22
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,885.68	2,935.00	10,950.68	78.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	700.00	3,060.00	81.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,645.68	3,635.00	14,010.68	79.40
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	17,645.68	2,900.00	14,745.68	83.57
+ GST 9.00/9.00% (S\$)	1,588.11	261.00	1,327.11	83.57
Nett Amount (S\$)	19,233.79	3,161.00	16,072.79	83.57
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		3,519.25		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	03/12/2024	
Date Inspected:	03/12/2024 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,525.00 FL	*2,650.00 FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	86.50 FL	*- FL
3	2		*REAR BUMPER CORNER BRACKET	Not Necessary	344.60 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	390.60 FL	*- FL
5	2		*REAR BUMPER BRACKET (CENTER)	Not Necessary	770.00 FL	*- FL
6	2		*REVERSE SENSOR	Not Necessary	870.00 FL	*- FL
7	6		*REVERSE SENSOR HOLDER	Not Necessary	411.00 FL	*- FL
8	1		*REVERSE SENSOR WIREHARNES	Not Necessary	698.30 FL	*- FL
9	2		*TAILLAMP	Not Necessary	2,936.00 FL	*- FL
10	2		*REAR FENDER COWLING	Not Necessary	685.42 FL	*- FL
11	1		*REAR BUMPER DIFFUSER (CARBON FIBER) (LOCAL REPAIR)	Damaged	2,800.00 FS	*500.00 FS
12	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
13	1		*SET TAILLAMP CLIP	Not Necessary	80.00 FS	*- FS
14	1		*SET REAR FENDER TOP GARNISH CLIP	Not Necessary	80.00 FS	*- FS
15	1		*REAR EXHAUST CHROME PIPE (SPECAIL TYPE)	Not Necessary	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,957.42	3,200.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,071.74	265.00
Total Parts (\$)	13,885.68	2,935.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	250.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	250.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	150.00	0.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	0.00
6	TRANFER BOOTLID MECHANISM	New	80.00	0.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	150.00
Gross Labour Cost (\$\$)			3,760.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >