

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24120020/TVH3M4**Date:** 26/12/2024**REFERENCE**

Insured/Claimant: CHAN JIANGUANG, BENJAMIN Policy No: MPC24D00024802
Date of Loss: 29/11/2024 Nature of Claim: OD Claim No: DMPC2401656H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG7698H**
Make & Model: TOYOTA LEXUS NX200T, 2.0 Executive (A) Engine No: 8ARW374038
Reg. Date: 04/11/2016 (Man. Year: 2016) Chassis No: JTJBARBZ702096104
Colour: White Odometer: 88528 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R18 Rear Tyre Size: 225/60R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,387.00	4,653.00	8,734.00	65.24
Miscellaneous Items	310.00	180.00	130.00	41.94
Labour	3,300.00	1,000.00	2,300.00	69.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,997.00	5,833.00	11,164.00	65.68
+ GST 9.00/9.00% (S\$)	1,529.73	524.97	1,004.76	65.68
Nett Amount (S\$)	18,526.73	6,357.97	12,168.76	65.68

INSPECTION

Date of Assignment: 02/12/2024 Present Location: Century Motors (Singapore) Pte Ltd (HQ)
CENTURY MOTORS (SINGAPORE) PTE LTD (HQ)
Date Inspected: 03/12/2024 Inspected At: 6 MARSILING LANE,
SINGAPORE 739145
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2024)
Parts:	143	TOYOTA LEXUS NX200T 2.0 Executive (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG7698H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Deformed	520.00 F	*520.00 F
2	1		*FRT BUMPER BRKT RH (WCP)	Not Necessary	100.00 F	*- F
3	1		*FRT BUMPER BRKT LH (WCP)	Not Necessary	100.00 F	*- F
4	1		*FRT GRILLE ASSY (WCP)	Cracked	600.00 F	*600.00 F
5	1		*FRT GRILLE CHROME (WCP)	Not Necessary	250.00 F	*- F
6	1		*FRT BUMPER LOWER MOULDING (WCP)	Not Necessary	350.00 F	*- F
7	1		*FRT BUMPER AIR DUCT LH (WCP)	Not Necessary	80.00 F	*- F
8	1		*FRT DAYLIGHT LH (WCP)	Not Necessary	850.00 F	*- F
9	1		*FRT DAYLIGHT RH (WCP)	Not Necessary	850.00 F	*- F
10	1		*HEADLAMP RH (WCP)	Not Necessary	800.00 F	*- F
11	1		*HEADLAMP LH (WCP)	Cracked	800.00 F	*800.00 F
12	1		*HEADLAMP BRKT RH (WCP)	Not Necessary	100.00 F	*- F
13	1		*HEADLAMP BRKT LH (WCP)	Not Necessary	100.00 F	*- F
14	1		*FRT ENGINE UNDERCOVER (WCP)	Not Necessary	200.00 F	*- F
15	1		*FRT FENDER WHEELARCH LH (WCP)	Torn	180.00 F	*180.00 F
16	1		*FRT FENDER LINER LH (WCP)	Not Necessary	150.00 F	*- F
17	1		*FRT TOWING COVER (WCP)	Not Necessary	50.00 F	*- F
18	1		*FRT SPOUNGE (WCP)	Cracked	60.00 F	*60.00 F
19	1		*FRT REINFORCEMENT (WCP)	Not Necessary	350.00 F	*- F
20	1		*FRT SUPPORT PANEL (WCP)	Not Necessary	750.00 F	*- F
21	1		*CONDENSER (WCP)	Bent	950.00 F	*950.00 F
22	1		*RADIATOR (WCP)	Not Necessary	750.00 F	*- F
23	1		*BONNET (WCP)	Repair	1,200.00 F	*- F
24	1		*BONNET HINGE RH (WCP)	Not Necessary	80.00 F	*- F
25	1		*BONNET HINGE LH (WCP)	Not Necessary	80.00 F	*- F
26	1		*FRT BUMPER LOWER LID (WCP)	Deformed	350.00 F	*350.00 F
27	1		*HEADLAMP WASHER PUMP LH (WCP)	Not Necessary	160.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*HEADLAMP WASHER PUMP RH (WCP)	Not Necessary	160.00 F	*- F
29	1		*FRT PARKING SENSOR (WCP)	Not Necessary	250.00 F	*- F
30	1		*FRT FENDER WHEELARCH RH (WCP)	Not Necessary	180.00 F	*- F
Supplementary #1						
31	1		*RAD SUPPORT TOP PANEL (WCP)	Bent	180.00 F	*180.00 F
32	1		*RAD GRILLE MOULDING (WCP)	Deformed	350.00 F	*350.00 F
33	1		*FRT EMBLEM(LOGO) (WCP)	Necessary	240.00 F	*240.00 F
F=Franchise part.						
					Sub Total (\$\$)	12,170.00 4,230.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	1,217.00 423.00
					Total Parts (\$\$)	13,387.00 4,653.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIRCON GAS (NECESSARY)	150.00	100.00
2	1	COOLANT (NOT NECESSARY)	80.00	0.00
3	1	FRT BUMPER CLIPS (NECESSARY)	40.00	40.00
4	1	FRT NUMBER PLATE AND HOLDER (BENT)	40.00	40.00
Sub Total (\$\$)			310.00	180.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	500.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,200.00	500.00
3	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	150.00	0.00
4	LABOUR TO REMOVE & REFIT FRT BOTH SIDE FENDER	New	200.00	0.00
5	LABOUR TO RESET ADJUST FRT RADAR ECU AND PARKING ECU	New	350.00	0.00
Gross Labour Cost (\$\$)			3,300.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >